



PRESTON MORRIS BUILDING
407 EAST HIGH STREET
CHARLOTTESVILLE, VIRGINIA

ECS PROJECT NO. 46:6713

FOR

CITY OF CHARLOTTESVILLE - FACILITIES DEVELOPMENT

NOVEMBER 4, 2021





November 4, 2021

Mr. Josh Bontrager
City of Charlottesville - Facilities Development
305 4th Street NW
Charlottesville, Virginia, 22903

ECS Project No. 46:6713

Reference: Facility Condition Assessment Report for Preston Morris Building, 407 East High Street, Charlottesville, Virginia

Dear Mr. Bontrager:

ECS Mid-Atlantic, LLC is pleased to provide the results of our Facility Condition Assessment (FCA) for the referenced property. The scope of the FCA was performed in general accordance with ASTM and industry guidelines and items contained within the ECS Proposal No. 46:7239-FP, dated June 12, 2020. We understand that our work is being performed under the City of Charlottesville Purchase Order Number 4500313133.

It has been our pleasure to be of service to you on this project. Should you have any questions or comments with regard to the findings and recommendations, please feel free to contact us at your convenience.

Respectfully,

ECS Mid-Atlantic, LLC

A handwritten signature in black ink, appearing to read 'Don M. Goglio'.

Donald M. Goglio
Project Manager
DGoglio@ecslimited.com
703-471-8400

A handwritten signature in blue ink, appearing to read 'Michael G. Doyle'.

Michael G. Doyle, AIA
Principal Architect
mdoyle@ecslimited.com
703-471-8400

Project Summary

Construction System	Good	Fair	Poor	Action	Immediate	Over Term Years 1-20
3.2.1 Topography	X			None		
3.2.2 Storm Water Drainage	X			None		
3.2.3 Access and Egress	X			None		
3.2.4 Paving, Curbing, and Parking	X			None		
3.2.5 Flatwork	X			Install rear landing		\$1,500
3.2.6 Landscaping and Appurtenances	X			None		
3.2.7 Recreational Facilities		NA		None		
3.2.8 Special Utility Systems		NA		None		
3.3.1 Foundation	X			None		
3.3.2 Building Frame	X			None		
3.3.3 Building Exteriors	X			Repair		\$18,000
3.3.4 Exterior Doors	X			None		
3.3.5 Exterior Windows	X			None		
3.3.6 Roofing Systems		X		Repair		\$7,500
3.4.1.1 Supply and Waste Piping	X			None		
3.4.1.2 Domestic Hot Water Production	X	X		Replace		\$2,000
3.4.2.1 Equipment	X	X		Replace		\$31,000
3.4.2.2 Distribution System	X			None		
3.4.2.3 Control Systems	X			None		
3.4.3.1 Service and Metering			X	None		
3.4.3.2 Distribution	X			None		
3.5 VERTICAL TRANSPORTATION SYSTEMS		NA		None		
3.6.1 Sprinklers and Suppression Systems	X			None		
3.6.2 Alarm Systems	X			None		
3.6.3 Security and Other Systems	X			None		
3.7.1 Tenant Spaces	X			None		
3.8 Accessibility (ADA) Compliance	X			None		
5.1 MOISTURE AND MOLD	X			None		
Totals					\$0	\$60,000

Summary	Today's Dollars	\$/Square Feet
Immediate Repairs	\$0	\$0.00

	Today's Dollars	\$/Square Feet	\$/Square Feet/Year
Replacement Reserves, today's dollars	\$60,000.00	\$21.69	\$1.08
Replacement Reserves, w/20, 2.5% escalation	\$73,148.85	\$26.45	\$1.32

TABLE OF CONTENTS

PAGE

1.0	EXECUTIVE SUMMARY	1
1.1	BACKGROUND	1
1.2	METHODOLOGY	1
1.3	PROPERTY DESCRIPTION	3
1.4	OPINIONS OF COST	4
1.5	COST TABLES	5
	Immediate Repair Cost	6
	Capital Reserve Schedule	7
2.0	PURPOSE AND SCOPE	9
2.1	SCOPE OF SERVICES	9
2.2	Deviations from Guide (ASTM E2018-15)	9
2.3	ASSESSMENT PROCEDURES	10
2.4	DEFINITIONS	10
	2.4.1 Partial List of ASTM Definitions	10
3.0	SYSTEM DESCRIPTION AND OBSERVATIONS	13
3.1	PROPERTY DESCRIPTION	13
	3.1.1 Property Location	13
	3.1.2 Construction History	13
	3.1.3 Current Property Improvements	13
3.2	SITE CONDITIONS	13
	3.2.1 Topography	13
	3.2.2 Storm Water Drainage	14
	3.2.3 Access and Egress	15
	3.2.4 Paving, Curbing, and Parking	15
	3.2.5 Flatwork	16
	3.2.6 Landscaping and Appurtenances	18
	3.2.7 Recreational Facilities	19
	3.2.8 Special Utility Systems	19
3.3	STRUCTURAL FRAME AND BUILDING EXTERIOR	20
	3.3.1 Foundation	20
	3.3.2 Building Frame	20

3.3.3	Building Exteriors	21
3.3.4	Exterior Doors	22
3.3.5	Exterior Windows	23
3.3.6	Roofing Systems	24
3.4	PLUMBING, MECHANICAL, AND ELECTRICAL SYSTEMS	25
3.4.1	Plumbing Systems	25
3.4.1.1	Supply and Waste Piping	25
3.4.1.2	Domestic Hot Water Production	26
3.4.2	HVAC Systems	26
3.4.2.1	Equipment	27
3.4.2.2	Distribution System	29
3.4.2.3	Control Systems	29
3.4.3	Electrical Systems	29
3.4.3.1	Service and Metering	29
3.4.3.2	Distribution	30
3.5	VERTICAL TRANSPORTATION SYSTEMS	31
3.6	LIFE SAFETY AND FIRE PROTECTION	31
3.6.1	Sprinklers and Suppression Systems	31
3.6.2	Alarm Systems	32
3.6.3	Security and Other Systems	33
3.7	INTERIOR BUILDING COMPONENTS	33
3.7.1	Tenant Spaces	33
3.8	Accessibility (ADA) Compliance	37
4.0	DOCUMENT REVIEW	44
4.1	DOCUMENTATION REVIEW	44
4.2	INTERVIEW SUMMARY	44
4.3	BUILDING, LIFE SAFETY, AND ZONING COMPLIANCE	44
5.0	ADDITIONAL CONSIDERATIONS	45
5.1	MOISTURE AND MOLD	45
6.0	RECOMMENDATIONS AND OPINIONS OF COST	46
7.0	FACILITY CONDITION INDEX (FCI)	48

TABLE OF APPENDICES

Appendix I: SITE MAP AND AERIAL PHOTOGRAPH

Appendix II: FIRE EXTINGUISHER INSPECTION

Appendix III: RS MEANS ESTIMATE FOR FACILITY CONDITION INDEX (FCI)

Appendix IV: SITE PHOTOGRAPHS

Appendix V: RESUMES

1.0 EXECUTIVE SUMMARY

1.1 BACKGROUND

ECS Mid-Atlantic, LLC (ECS) performed a Facility Condition Assessment (FCA) in general conformance with ASTM guidelines and general scope items contained within the ECS Proposal 46:7239-FP dated June 12, 2020 for the Preston Morris Building property in Charlottesville, Virginia - hereinafter known as the Property.

The FCA was conducted by ECS in response to the authorization of our Proposal by Ms. Susan Dyer on November 23, 2020. The report was completed and reviewed by the following team members:

William R. Pratt, P.E.	Principal Engineer
	Phone: 703-471-8400
	E-mail: wpratt@ecslimited.com
Michael G. Doyle, AIA	Principal Architect
	Phone: 703-471-8400
	E-mail: mdoyle@ecslimited.com
Donald M. Goglio	Project Manager
	Phone: 703-471-8400
	E-mail: DGoglio@ecslimited.com

Reliance

This report is provided for the exclusive use of City of Charlottesville - Facilities Development. This report is not intended to be used or relied upon in connection with other projects or by other unidentified third parties. The use of this report by any undesignated third party or parties will be at such party's sole risk and ECS disclaims liability for any such third party use or reliance.

1.2 METHODOLOGY

ECS observations and historical property data provided by the owner were utilized to determine the effective age of the property components. Various factors including exposure to weather elements, system manufacturer quality, level of maintenance, and usage determine the effective age of property components. Depending on the impact of these various factors, the effective age of property components can reduce the Remaining Useful Life (RUL) of a property component. The general requirements of the owner to address facility needs were requested to be prioritized based on the RUL and type of property component. The following Priorities were established by the Owner as follows:

Priority 1: Immediately Critical Items (Year 0)

Items in this Priority category include physical deficiencies that require immediate action as a result of (i) existing or potentially unsafe conditions, (ii) significant negative conditions impacting tenancy, (iii) material building code violations or Title II American with Disabilities Act (ADA) items.

Priority 2: Critical Items (Year 0-1)

Items in this Priority category include physical deficiencies that require immediate action as a result of (i) poor or deteriorated condition of critical element or system, or (ii) a condition that is left “as is,” with an extensive delay in addressing same, would result in or contribute to critical element or system failure within one year.

Priority 3: Near Term Items (Years 2-5)

Items in this category include physical deficiencies that require near term action as a result of (i) poor or deteriorated condition of critical element or system, or (ii) a condition that is left “as is,” with an extensive delay in addressing same, would result in or contribute to critical element or system failure within two to five years.

Priority 4: Reserve Items (Years 5-20)

Items in this Priority category include Capital Reserves for recurring probable expenditures, which are not classified as operational or maintenance expenses, which should be annually budgeted for in advance. Capital reserves are reasonably predictable both in terms of frequency and cost. However, they may also include components or systems that have an indeterminable life but nonetheless have a potential liability for failure within an estimated time period. A component method has also been included within this report as well.

Reserve items excludes systems or components that are estimated to expire after the reserve term and that are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that were not deemed to have a material affect on the use were also excluded. Costs that are caused by acts of God, accidents or other occurrences that are typically covered by insurance, rather than reserved funds, are also excluded.

Replacement costs were solicited from ownership/property management, ECS’ discussions with service companies, manufacturers’ representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by ownership’s or property management’s maintenance staff were also considered.

ECS’s reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the evaluation period. Additional information concerning systems or components respective replacement costs (in today’s dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Capital Reserve Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined in the Immediate Needs Cost Estimates.

1.3 PROPERTY DESCRIPTION

The Preston Morris Building property, located at 407 East High Street, in Charlottesville, Virginia, consists of a Two-story building. The building totals approximately 2,766 square feet. Parking is provided with At-grade parking with asphalt pavement. The Office building was reportedly constructed in 1974 and renovated as recently as 2006.

SURVEY INFORMATION	
Date of Assessment	August 24, 2021
Assessor	William R. Pratt, P.E.
Weather Conditions	Tuesday, 95 Degree F
Property Contact	Josh Bontrager, Project Manager for City of Charlottesville - Facilities Development

SITE INFORMATION	
Land Area	0.20 acres
Major Cross Streets	9th Street NE
Pavement - Parking	At-grade parking with asphalt pavement
Number of Parking Spaces	18
Number of Accessible Spaces	Four
Number of Van Accessible Spaces	Four
Pedestrian Sidewalks	Brick sidewalks

BUILDING INFORMATION	
Building Type	Office
Number of Buildings	One
Building Height	Two-story
Square Footage	2,766
Year Constructed	1974
Year Remodeled	2006

BUILDING CONSTRUCTION

Foundation	Assumed shallow spread footings
Structural System	Wood framing with brick masonry bearing exterior walls
Roof	Asphalt shingle
Exterior Finishes	Brick
Windows	Vinyl frame double pane - operable
Entrance	Wood door

BUILDING SYSTEMS

HVAC System	Split systems
Domestic Hot Water	Electric domestic water heater
Water Distribution	Copper
Sanitary Waste Line	Cast iron/PVC
Electrical Service	120/240-volt single-phase 3-wire 400 amps service
Branch Wiring	Copper
Elevators	N/A
Fire Suppression System	Fire extinguishers with smoke detectors

UTILITY SERVICE PROVIDERS

Water	Charlottesville Water
Sewer	Charlottesville Public Utilities - Wastewater
Electric	Dominion Virginia Power
Natural Gas	City of Charlottesville

1.4 OPINIONS OF COST

The opinions of cost are provided in the attached reserve replacement table and a summary of immediate repairs included in this report. The reserve replacement table covers capital expenditure items only. Items less than \$1,000 in cost have been excluded, except for immediate repairs, ADA or safety issues. Please refer to section 6.0 of this report for a detailed explanation on how these costs are derived.

1.5 COST TABLES

Immediate Repair Cost

Item	Quantity	Unit	Unit Cost	Replacement Percent	Immediate Total
Total Repair Cost					\$0.00

Capital Reserve Schedule																													
Item	EUL	EFF AGE	RUL	Quantity	Unit	Unit Cost	Cycle Replace	Replace Percent	Year 1 2021	Year 2 2022	Year 3 2023	Year 4 2024	Year 5 2025	Year 6 2026	Year 7 2027	Year 8 2028	Year 9 2029	Year 10 2030	Year 11 2031	Year 12 2032	Year 13 2033	Year 14 2034	Year 15 2035	Year 16 2036	Year 17 2037	Year 18 2038	Year 19 2039	Year 20 2040	Total Cost
3.2.5 Flatwork																													
INSTALL LANDING AT REAR DOOR EXTERIOR			0	1	EA	\$1,500.00	\$1,500	100%	\$1,500																				\$1,500
3.3.3 Building Exteriors																													
PAINT EXTERIOR AND REPAIR DETERIORATED WOOD TRIM AS NEEDED	7	6	1	1	EA	\$1,000.00	\$1,000	300%	\$1,000						\$1,000								\$1,000						\$3,000
REPOINT BRICKWORK	20	15	5	1	LS	\$15,000.00	\$15,000	100%					\$15,000																\$15,000
3.3.6 Roofing Systems																													
REPLACE ASPHALT SHINGLED ROOFING SYSTEM	20	15	5	1,500	SF	\$5.00	\$7,500	100%					\$7,500																\$7,500
3.4.1.2 Domestic Hot Water Production																													
REPLACE WATER HEATER	12	11	1	1	EA	\$1,000.00	\$1,000	200%	\$1,000												\$1,000								\$2,000
3.4.2.1 Equipment																													
REPLACE GAS FURNACE - AIR HANDLER UNITS	15	11	4	2	EA	\$5,000.00	\$10,000	200%				\$10,000															\$10,000		\$20,000
REPLACE CONDENSERS	15	11	4	1	EA	\$5,500.00	\$5,500	200%				\$5,500															\$5,500		\$11,000
Total (Uninflated)									\$3,500.00	\$0.00	\$0.00	\$15,500.00	\$22,500.00	\$0.00	\$0.00	\$1,000.00	\$0.00	\$0.00	\$0.00	\$0.00	\$1,000.00	\$0.00	\$1,000.00	\$0.00	\$0.00	\$0.00	\$15,500.00	\$0.00	\$60,000.00
Inflation Factor (2.5%)									1.0	1.025	1.051	1.077	1.104	1.131	1.16	1.189	1.218	1.249	1.28	1.312	1.345	1.379	1.413	1.448	1.485	1.522	1.56	1.599	
Total (inflated)									\$3,500.00	\$0.00	\$0.00	\$16,691.80	\$24,835.79	\$0.00	\$0.00	\$1,188.69	\$0.00	\$0.00	\$0.00	\$0.00	\$1,344.89	\$0.00	\$1,412.97	\$0.00	\$0.00	\$0.00	\$24,174.71	\$0.00	\$73,148.85

City of Charlottesville - Facilities Development
ECS Project No. 46:6713
November 4, 2021

		EFF							Year	Year	Year	Year	Year	Year	Year	Year	Year	Year	Year	Year	Year	Year	Year	Year	Year	Year	Year	Year	Year	Year	
Item	EUL	AGE	RUL	Quantity	Unit	Unit Cost	Cycle Replace	Replace Percent	1 2021	2 2022	3 2023	4 2024	5 2025	6 2026	7 2027	8 2028	9 2029	10 2030	11 2031	12 2032	13 2033	14 2034	15 2035	16 2036	17 2037	18 2038	19 2039	20 2040	Total Cost		
Evaluation Period:									20																						
# of Square Feet:									2,766																						
Reserve per Square Feet per year (Uninflated)									\$1.08																						
Reserve per Square Feet per year (Inflated)									\$1.32																						

2.0 PURPOSE AND SCOPE

2.1 SCOPE OF SERVICES

This Facility Condition Assessment (FCA) was conducted in general accordance with items and terminology requested by the Owner herein and ASTM E 2018-15, "Standard Guide for Property Condition Assessments: Baseline Property Condition Assessment Process".

The primary purpose of a FCA is to note construction deficiencies and to identify components which appear to exhibit less than expected service life or which have been poorly maintained. The assessment is not intended to develop detailed remedial plans for identified problems. The services are qualitative in nature and do not include engineering calculations or design. Photographic documentation of our observations is attached.

The following building systems were observed in accordance with ASTM E 2018-15:

- Site Conditions
- Structural Frame and Building Envelope
- Plumbing, Mechanical and Electrical Systems
- Vertical Transportation Systems
- Life Safety and Fire Protection
- Interior Elements
- ADA Considerations
- Building Code Violations

Out of Scope Items

Environmental issues and concerns are considered to be outside of the ASTM scope of services for a Facility Condition Assessment. Although properties may have possible environmental contamination, including, but not limited to radon, mold, lead based paint, asbestos, lead piping, PCB's or volatile chemicals, these issues and concerns should be addressed by an Environmental Assessment, as defined by ASTM Guidelines. ECS recommends that properties be studied by a qualified environmental assessor who can appropriately access, identify, and quantify issues related to environmental safety concerns.

ECS is providing a Facility Condition Assessment consistent with commercial and customary practices and the ASTM E-2018, current at the time the services are provided. The parties expressly acknowledge and agree that ECS is not providing a Reserve Study, which is subject to the National Reserve Study Standards and requires much more detail than a typical Facility Condition Assessment.

2.2 Deviations from Guide (ASTM E2018-15)

ASTM E2018-15 requires that any deviations from the Guide be noted within the report. ECS reduced the cost threshold from \$3,000 to \$1,000 to allow for smaller items needing repair, replacement or refurbishment. Therefore items with costs less than \$1,000 are typically not included in this report unless related to life, safety or accessibility items.

ECS interviewed personnel associated with the Preston Morris Building facility and other government agencies based upon availability. These individuals are identified in Section 4.2. Information obtained from the interviews are included in the applicable sections of this report.

2.3 ASSESSMENT PROCEDURES

The FCA included site reconnaissance, limited interviews with property management, and inquiries or attempted inquiries with the local building and fire departments. Operational testing of building systems or components was not conducted. During the FCA, ECS conducted observations of the following facility features: site development systems; building structure systems; building exterior systems; building interior systems; roof systems; mechanical systems; electrical systems; plumbing systems; and life and fire safety systems.

This report is intended for review as a complete document. Therefore, interpretations and conclusions drawn from the review of any individual section are the sole responsibility of the User.

2.4 DEFINITIONS

Fair, adj - the property or component is functional but will likely require immediate maintenance or repairs during the duration of the term.

Good, adj - the property or component is functional and should continue to provide its intended service with continued routine maintenance through the duration of the term.

Poor, adj - the property or component is not functional. Immediate or near term repairs are required to bring the component back into service or replacement is expected during the duration of the term.

2.4.1 Partial List of ASTM Definitions

de minimis condition - a physical deficiency that is not material to the conclusions of the report.

deferred maintenance, n - physical deficiencies that could have been remedied with routine maintenance, normal operating maintenance, etc., excluding de minimis conditions that generally do not present a material physical deficiency to the subject property.

easily visible, adj - describes items, components, and systems that are conspicuous, patent, and which may be observed visually during the walk-through survey without: intrusion, relocation or removal of materials, exploratory probing, use of special protective clothing, or use of any equipment (hand tools, meters of any kind, telescope instruments, stools, ladders, lighting devices, etc.).

effective age, n - the estimated age of a building component that considers actual age as affected by maintenance history, location, weather conditions, and other factors. Effective age may be more or less than actual age.

expected useful life (EUL), n - the average amount of time in years that an item, component or system is estimated to function without material repair when installed new and assuming routine maintenance is practiced.

immediate cost, n - opinions of costs that require immediate action as a result of any of the following: (1) material existing or potentially unsafe conditions, (2) material building or fire code violations, (3) physical deficiencies that if left uncorrected would be expected to result in or contribute to critical element or system failure within one year or will result most probably in significant escalation of its remedial cost.

observation, n - the visual survey of items, systems, conditions, or components that are readily accessible and easily visible during a walk-through survey of the subject property.

observe, v - to conduct an observation pursuant to this guide within the context of easily visible and readily accessible.

obvious, adj - plain, evident, and readily accessible; a condition easily visible or fact not likely to be ignored or overlooked by a field observer when conducting a walk-through survey or that which is practically reviewable and would be understood easily by a person conducting the FCA.

opinions of costs, n - opinion of costs that may be encountered in correction of physical deficiencies.

physical deficiency, n - a conspicuous defect or deferred maintenance of a subject property's material systems, components, or equipment as observed during the completion of the FCA. - This definition specifically excludes deficiencies that may be remedied with routine maintenance, miscellaneous minor repairs, normal operating maintenance, etc., and excludes de minimis conditions that generally do not present material physical deficiencies of the subject property.

Point of Contact (POC), n - owner, owner's agent, or user-identified person or persons knowledgeable about the physical characteristics, maintenance, and repair of the subject property.

practically reviewable, adj - describes information that is provided by the source in a manner and form that, upon review, yields information relevant to the subject property without the need for significant analysis, measurements, or calculations. Records or information that feasibly cannot be retrieved by reference to the location of the subject property are not generally considered practically reviewable.

primary commercial real estate improvements, n - the site and building improvements that are of fundamental importance with respect to the commercial real estate. This definition specifically excludes ancillary structures, that may have been constructed to provide support uses such as maintenance sheds, security booths, utility garages, pool filter and equipment buildings, etc.

property, n - the site improvements, which are inclusive of both site work and buildings.

readily accessible, adj - describes areas of the subject property that are promptly made available for observation by the field observer at the time of the walk-through survey and do not require the removal or relocation of materials or personal property, such as furniture, floor, wall, or ceiling coverings; and that are safely accessible in the opinion of the field observer.

readily available, adj - describes information or records that are easily and promptly provided to the consultant upon making a request in compliance with an appropriate inquiry and without the need for the consultant to research archive files.

reasonably ascertainable, adj - describes information that is publicly available, as well as readily available, provided to the consultant's offices from either its source or an information research/retrieval service within reasonable time, practically reviewable, and available at a nominal cost for either retrieval, reproduction or forwarding.

remaining useful life (RUL), n - a subjective estimate based upon observations, or average estimates of similar items, components, or systems, or a combination thereof, of the number of remaining years that an item, component, or system is estimated to be able to function in accordance with its intended purpose before warranting replacement. Such period of time is affected by the initial quality of an item, component, or system, the quality of the initial installation, the quality and amount of preventive maintenance exercised, climatic conditions, extent of use, etc.

representative observations, n - observations of a reasonable number of samples of repetitive systems, components, areas, etc., which are conducted by the field observer during the walk-through survey. The concept of representative observations extends to all conditions, areas, equipment, components, systems, buildings, etc., to the extent that they are similar and representative of one another.

routine maintenance, n - a repair that does not require specialized equipment, profession services, or contractors, but rather can be corrected within budget and skill set of typical property maintenance staff.

short term cost, n - opinions of costs to remedy physical deficiencies, such as deferred maintenance, that may not warrant immediate attention, but require repairs or replacements that should be undertaken on a priority basis in addition to routine preventive maintenance.

technically exhaustive, adj - describes the use of measurements, instruments, testing, calculations, exploratory probing or discovery, or other means to discover, or a combination thereof, or troubleshoot physical deficiencies or develop architectural or engineering findings, conclusions, and recommendations, or combination thereof.

3.0 SYSTEM DESCRIPTION AND OBSERVATIONS

3.1 PROPERTY DESCRIPTION

The Property contains a Two-story Office building.

3.1.1 Property Location

The Property is located at 407 East High Street in Charlottesville, Virginia.

Surrounding Properties	
North	J&DR Courts-Sherriff's Office-Parking-Complex
East	J&DR Courts-Sherriff's Office-Parking-Complex
South	East High Street
West	Wheeler Building

A Site Location Map and Aerial View are included in Appendix I.

3.1.2 Construction History

We understand that the building was constructed approximately 47 years ago in 1974.

3.1.3 Current Property Improvements

The Office building, located at 407 East High Street, in Charlottesville, Virginia, consists of a Two-story building. The building totals approximately 2,766 square feet. Parking is provided with At-grade parking with asphalt pavement.

3.2 SITE CONDITIONS

3.2.1 Topography

TOPOGRAPHY		
Item	Description	Condition
Slope of the property	The property generally slopes to the north	Good
Adjoining Properties	Generally level with or down slope from the property	Good

Comments

The property is generally level and slopes to the north. The adjoining properties are generally level with or located down gradient from the property.

3.2.2 Storm Water Drainage

STORM WATER DRAINAGE		
Item	Description	Condition
Storm Water Collection System	Municipal system	Good
Storm Water (Retention) Pond		N/A
Storm Water Filtration Structure		N/A
Pavement Drainage	Sheet flow	Good
Landscape Drainage	Sheet flow	Good
Sump Pumps		N/A

Comments

The storm water collection system includes a municipal system. Aluminum downspouts were observed to be damaged or missing elbows at their base. Downspouts should be repaired immediately to prevent water intrusion at foundation.

Photographs



Downspout in south side of building



Building exterior north side of the building -
note downspout condition

3.2.3 Access and Egress

SITE ACCESS AND EGRESS		
Item	Description	Condition
Entrance Aprons	Concrete	Good
Fire Truck Access	North, south, and west sides of the building	Good
Easements		Good

Comments

Vehicular access to the site is located on the north, south, and west sides of the building. The entrance aprons are constructed of concrete and were observed to be in generally good condition. Fire truck access is available on the north, south, and west sides of the building.

3.2.4 Paving, Curbing, and Parking

PARKING		
Item	Description	Condition
Striping	Painted	Good
Quantity of Parking Spaces	18	Good
Quantity of Loading Spaces		N/A
Arrangement of Spaces	Perpendicular parking on north, east, and south sides of lot	Good
Site Circulation	Parking entrance from 4th Street	Good
Lighting		N/A
Accessible Spaces	Four	Good
Accessible Aisles	Three	Good

SURFACE PAVEMENT		
Item	Description	Condition
Pavement Surface	At-grade parking with asphalt pavement	Good
Drainage	The parking lot generally drains to a curb inlet at the northwest corner	Good
Repair History		Good
Concrete Driveway	south side of the property	Good

Comments

Asphalt-paved drive lanes and parking are located on the north side of the site. The asphalt pavement is shared with the adjacent Wheeler Building. The expected useful life of asphalt pavement is 20 years. The asphalt pavement was observed to be in generally good condition.

Photographs



Accessible parking

3.2.5 Flatwork

SIDEWALKS		
Item	Description	Condition
Walkways	Brick sidewalks	Fair
Ramp	Located on southwest side of the building	Good
Steps	Brick steps at front and side entrances	Good
Landings	Brick landings at front ramp entrance	Good
Handrails	Painted steel railing at front and side entrances	Good

Comments

Brick sidewalks are located on the south side and east side of the building. The Brick sidewalks thickness was undetermined. The Brick sidewalks were generally in fair condition with minor cracking and some missing mortar requiring point up. A brick ramp is located at the southwest side of the building. The brick ramp was generally in good condition.

The exit door on the north side (rear) of the building was not provided with a landing on the exterior. We recommend installing a landing in this area to provide firm footing upon exiting the building.


Photographs



Brick ramp at southwest side of the building



Brick sidewalk south side of the building



Cracked brick sidewalk at south side of building



Building exterior southeast side of the building



Accessible brick ramp at southwest side of the building



Brick ramp at southwest side of the building

Recommendations

Cost Recommendation	EUL	EFF AGE	RUL	Year	Cost
INSTALL LANDING AT REAR DOOR EXTERIOR	-	-	0	1	\$1,500
Total					\$1,500

3.2.6 Landscaping and Appurtenances

LANDSCAPING		
Item	Description	Condition
Trees	Located on south side of property	Good
Planting Beds	Located at the south side of the property	Good
Lawn Areas	Located at south side of the property	Good
Retaining Walls	Located on the southwest side of the property	Good
Fences and Gates	Located atop retaining wall	Good
Trash Containers	Located at north side of the property	Good

Comments

The landscaping consists generally of a two trees and grassed area at the south side of the site. The landscaping was observed to be in generally good condition.

Photographs



Landscape area

3.2.7 Recreational Facilities

Comments

The Property does not contain recreational facilities.

3.2.8 Special Utility Systems

Item	Description	Condition
Water Well		N/A
Lift Station		N/A
Septic Field		N/A
Solar Power		N/A
Wind Power		N/A

Comments

The Property does not contain special utility systems.

3.3 STRUCTURAL FRAME AND BUILDING EXTERIOR

3.3.1 Foundation

FOUNDATION		
Item	Description	Condition
Load Bearing Support	Assumed shallow spread footings	Good
Basement	Walk-out on north side of building	Good
Crawl Space		N/A

Comments

The foundation of the building includes Assumed shallow spread footings. Large cracks were not observed in the exterior walls. The foundation system appeared to provide adequate structural support to the building. The foundation was generally in good condition.

3.3.2 Building Frame

BUILDING FRAME		
Item	Description	Condition
Floor Framing	Wood	Good
Roof Framing	Wood	Good
Load Bearing Walls and Columns	Brick masonry	Good

Comments

The structure of the building consists of Wood framing with brick masonry bearing exterior walls with brick masonry columns. The structural frame of the building was generally in good condition.

Photographs



Structural framing



Structural framing

3.3.3 Building Exteriors

EXTERIOR FINISHES		
Item	Description	Condition
Brick	All sides	Good
Wood Trim	Soffit, fascia	Good
Paint	Windows, trim	Good
Sealants	Various	Good

Comments

The exterior of the building mainly consists of Brick. The building exteriors were generally in fair condition. The expected useful life of mortared joints is approximately 20 years before re-pointing is required.

The wood trim and wood covered soffits are painted. The paint was generally in good condition with renovations completed in 2006. Painting of exterior components is typically recommended every 5 to 7 years. We recommend the wood trim and soffits be painted during the report period.

Photographs



Building exterior southeast side of the building



Building exterior north side of the building

Recommendations

Cost Recommendation	EUL	EFF AGE	RUL	Year	Cost
PAINT EXTERIOR AND REPAIR DETERIORATED WOOD TRIM AS NEEDED	7	6	1	1	\$1,000
				8	\$1,000
				15	\$1,000
REPOINT BRICKWORK	20	15	5	5	\$15,000
Total					\$18,000

3.3.4 Exterior Doors

DOORS		
Item	Description	Condition
Main Entrance Doors	Wood door	Good
Rear door	Metal with glass	Good

Comments

The main entrance is a Wood door. The main entrance door was generally in good condition. Exterior doors typically have an expected useful life of 20 to 30 years.

Photographs



Main entrance door



Building exterior north side of the building -
note deterioration

3.3.5 Exterior Windows

WINDOWS		
Item	Description	Condition
Window Frame	Vinyl frame double pane - operable	Good
Glass Pane	Double pane with storm windows	Good
Operation	Double hung	Good
Screen	Exterior	Good
Exterior Header	Painted steel lintel	Good
Exterior Sill	Brick sill course	Good
Gaskets or Glazing		Good

Comments

The window system for the building primarily consists of Vinyl frame double pane - operable window units. The expected useful life of windows is typically 30 years. The window units were in generally in good condition.

Photographs



Typical exterior window



Typical exterior window condition

3.3.6 Roofing Systems

ROOFING		
Item	Description	Condition
Asphalt Shingle	Architectural shingles	Fair
Insulation	Blown fiber observed in attic	Good
Substrate/Deck	Wood	Good
Slope/Pitch		Good
Drainage	Gutters and downspouts	Fair
Plumbing Vents	Neoprene collar	Good
Exhaust Vents		N/A
Flashing	Metal	Fair

Comments

The main roofing system consists of a Asphalt shingle roofing system over the building. The roofing system was reportedly installed in 2006 during renovation. The roofing system was in good to fair condition. The expected useful life of an asphalt shingle roofing system is 20 years. Based on the age of the roofing system, we recommend replacement during the report period.

Drainage for the roofing system is provided by gutters and downspouts. The gutters were observed to be in good condition. Aluminum downspouts were observed to be damaged or missing elbows at their base. Downspouts should be repaired immediately to prevent water intrusion at foundation.

Recommendations

Cost Recommendation	EUL	EFF AGE	RUL	Year	Cost
REPLACE ASPHALT SHINGLED ROOFING SYSTEM	20	15	5	5	\$7,500
Total					\$7,500

3.4 PLUMBING, MECHANICAL, AND ELECTRICAL SYSTEMS

3.4.1 Plumbing Systems

3.4.1.1 Supply and Waste Piping

PLUMBING - WATER SUPPLY SYSTEM		
Item	Description	Condition
Piping Material	Copper	Good
Pipe Insulation		N/A
Water Shut-offs	Various	Good
Water Flow and Pressure		Good

PLUMBING - WASTE SUPPLY SYSTEM		
Item	Description	Condition
Piping Material	Cast iron/PVC	Good
Vertical Vent Stacks	Cast iron/PVC	Good
Clean-outs	Cast iron/PVC	Good

Comments

Water Lines

The main water supply lines inside the building are Copper. The expected useful life of copper piping is approximately 40 years. The water supply pipes were generally in good condition.

Waste Lines

The waste lines in the building are Cast iron/PVC. The expected useful life of Cast iron/PVC waste line is approximately 50 years. The waste lines were generally in good condition.

3.4.1.2 Domestic Hot Water Production

HOT WATER PRODUCTION		
Item	Description	Condition
Heating Equipment	Electric domestic water heater located on the lower level	Good/Fair
Water Storage		Good

Comments

Domestic hot water to the building is provided by an Electric domestic water heater located in the basement. The Electric domestic water heater was manufactured by Rheem. The expected useful life of an Electric domestic water heater is approximately 12 to 15 years. We recommend the Electric domestic water heater be replaced during the report period.

Photographs



Electric domestic water heater

Recommendations

Cost Recommendation	EUL	EFF AGE	RUL	Year	Cost
REPLACE WATER HEATER	12	11	1	1 13	\$1,000 \$1,000
Total					\$2,000

3.4.2 HVAC Systems

3.4.2.1 Equipment

EQUIPMENT		
Item	Description	Condition
Condenser Units	Located exterior ground level	Good/Fair
Air Handlers	Located in attic and lower level	Good/Fair

Comments

The building is served by Split systems and includes three condensers and three air handlers.

Condenser Units

Three condenser units are located at the ground level on the east and west sides of the building. The condensing units varied in age and were manufactured by Bryant and Champion. The expected useful life of a condensing unit is 15 years with proper maintenance. The condensing units were observed to be in good to fair condition. We recommend that the condensing units be replaced near the end of the report period.

Air Handler Units

Two heat pump air handler units were located in the lower level and one in the attic. The air handlers were manufactured by Bryant, Champion, and Carrier in various ages. The expected useful life of an air handler is 15 years with proper maintenance. The air handlers were observed to be in good to fair condition. We recommend that the air handlers be replaced during the report period.

Photographs



Condenser Unit



Air Handler Unit



Air Handler Unit



Condenser Unit



Condenser Unit



Typical mechanical duct

Recommendations

Cost Recommendation	EUL	EFF AGE	RUL	Year	Cost
REPLACE GAS FURNACE - AIR HANDLER UNITS	15	11	4	4 19	\$10,000 \$10,000
REPLACE CONDENSERS	15	11	4	4 19	\$5,500 \$5,500
Total					\$31,000

3.4.2.2 Distribution System

HVAC DISTRIBUTION		
Item	Description	Condition
Ducts	Insulated metal and flex duct	Good
Return Air	Metal	Good

Comments

The distribution system includes ducted supply and return. The ductwork was observed to be in generally good condition.

3.4.2.3 Control Systems

HVAC CONTROL SYSTEMS		
Item	Description	Condition
Thermostats	Digital for cooling	Good

Comments

The thermostats are digital. The thermostats were observed to be in generally good condition.

3.4.3 Electrical Systems

3.4.3.1 Service and Metering

SERVICE AND METERING		
Item	Description	Condition
Service Entrance	Located on the north side of the building	Good
Master (House) Meter	Located on the north side of the building	Good
Emergency Power		N/A
Transfer Switch		N/A

Comments

Electricity is provided to the building by Dominion Virginia Power through a pole mounted transformer. The main electrical entrance is located on the north side of the building and provides 120/240-volt, single-phase, 3-wire, 400 amps service.

Photographs



Digital electric meter



Main electrical disconnect

3.4.3.2 Distribution

ELECTRICAL DISTRIBUTION SYSTEM		
Item	Description	Condition
Electrical Sub-panels	Square D	Good
Branch Wiring	Copper	Good
GFCI Devices		Good

Comments

Power is distributed by copper wire from smaller circuit breaker panels manufactured by Square D located throughout the building. The Square D panels are in generally good condition.

Photographs



Electrical panel



Typical circuit breaker panel manufactured by
Square D

3.5 VERTICAL TRANSPORTATION SYSTEMS

Comments

The building does not contain vertical transportation systems.

3.6 LIFE SAFETY AND FIRE PROTECTION

3.6.1 Sprinklers and Suppression Systems

SPRINKLER AND SUPPRESSION SYSTEMS		
Item	Description	Condition
Sprinkler System (wet)		N/A
Sprinkler Heads		N/A
Date of Last Inspection (sprinkler system)		N/A
Sprinkler Pipe Material		N/A
Fire Extinguishers	Located throughout the building	Good
Date of Last Inspection (Fire Extinguishers)	June 10, 2021	Good
Fire Standpipes		N/A
Fire Hydrants	Located on East High Street	Good

Comments

The fire suppression system consists of Fire extinguishers. The fire suppression system was observed but not tested. Fire extinguishers were observed throughout the building. The fire extinguishers were observed to have inspection tags issued by Fire Solutions in June 2021. These devices are required to be inspected annually.

Photographs



Fire extinguisher



Fire hydrant

3.6.2 Alarm Systems

ALARM SYSTEMS		
Item	Description	Condition
Annunciator Panel		N/A
Central Fire Alarm Control Panel		N/A
Bells		N/A
Strobes		N/A
Exit Signs	Located throughout the building	Good
Exit Lights	Located throughout the building	Good
Pull Stations		N/A
Smoke Detectors	Located throughout the building	Good

Comments

The smoke alarm system was observed but not tested. Smoke detectors, exit signs, and emergency lighting are located throughout the building. The fire alarm systems were generally in good condition.

Photographs



Typical exit sign

3.6.3 Security and Other Systems

SECURITY AND OTHER SYSTEMS		
Item	Description	Condition
Alarm System	Located in administrative offices	Good
Access Control		Good

Comments

The building has an electronic alarm system and secure access with hardware locks. The security system was generally in good condition.

3.7 INTERIOR BUILDING COMPONENTS

3.7.1 Tenant Spaces

ENTRANCE AREAS		
Item	Description	Condition
Floor Finishes	Carpet	Good
Wall Finishes	Painted gypsum board	Good

ENTRANCE AREAS

Item	Description	Condition
Ceiling Finishes	Painted gypsum board	Good
Lighting	Various fixtures	Good

OFFICES

Item	Description	Condition
Floor Finishes	Carpet	Good
Wall Finishes	Painted gypsum board	Good
Ceiling Finishes	Painted gypsum board	Good
Lighting	Fluorescent fixtures	Good
Doors	Masonite	Good
Door Hardware	Operable	Good

MEETING ROOM

Item	Description	Condition
Floor Finishes	Carpet	Good
Wall Finishes	Painted gypsum board	Good
Ceiling Finishes	Painted gypsum board	Good
Lighting	Fluorescent fixtures	Good
Doors	Masonite	Good
Door Hardware	Operable	Good

RESTROOMS

Item	Description	Condition
Floor Finishes	Vinyl tile	Good
Wall Finishes	Painted gypsum board	Good
Ceiling Finishes	Painted gypsum board	Good
Fixtures	Toilets, urinal, wall hung lavatories	Good
Accessories	Grab bars, mirrors, soap and paper dispensers	Good
Ventilation	Exhaust fans	Good

RESTROOMS		
Item	Description	Condition
Lighting	Fluorescent fixtures	Good
Doors	Masonite	Good
Door Hardware	Operable	Good

CORRIDOR AREA		
Item	Description	Condition
Floor Finishes	Ceramic tile	Good
Wall Finishes	Painted plaster and/or painted gypsum board	Good
Ceiling Finishes	Painted plaster and/or painted gypsum board	Good
Lighting	Fluorescent fixtures	Good
Doors	Masonite	Good
Door Hardware	Operable	Good

Comments

The interior common building areas include an entrance area, offices, meeting rooms, restrooms, and corridors

The finishes in the entrance area includes carpet, painted gypsum board walls, and painted gypsum board ceilings. The finishes in the entrance area was observed to be in generally good condition.

The finishes in the meeting areas include carpet, painted gypsum board walls, and painted gypsum board ceilings. The finishes in the meeting areas were observed to be in generally good condition.

The office finishes include carpet floors, painted gypsum board walls, and painted gypsum board ceilings. The finishes in the offices were observed to be in generally good.

The finishes in the restrooms include vinyl tile floors, painted gypsum board walls, and painted gypsum board ceilings. The restrooms were observed to be in generally good condition.

The finishes in the corridor areas include ceramic tile floors, and painted r gypsum board walls and painted gypsum board ceilings. The finishes in the corridor areas were observed to be in generally good condition.


Photographs



Interior finishes entrance area



Typical handrail stair



Typical stair



Typical men's restroom




Typical men's restroom



Typical meeting room



Typical office interior



Typical corridor interior

3.8 Accessibility (ADA) Compliance

Comments

Facilities, including site features and buildings, completed and occupied after January 26, 1992 are required to comply fully with the Americans with Disabilities Act (ADA). Facilities constructed after this date must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG). Existing facilities constructed prior to this date are held to the lesser standard of complying with the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. Title III, for the purposes of the ECS scope of work is to address public accommodations. ECS will note work that shall remove architectural barriers in existing facilities, including communication barriers, that are structural in nature, where such removal is readily achievable and able to be carried out without much difficulty or expense.

The Preston Morris Building property is considered by the City of Charlottesville - Facilities Development to be within "areas of public accommodations" or a "commercial facility" and is therefore is subject to compliance with Title III of the ADA.

The parking area serving the property has a total of 18 parking spaces. Of the parking spaces, Four are van accessible. Accessibility requires that one accessible parking space be provided in parking areas with a total of one to 25 spaces. One in six of the accessible parking spaces are required to be van accessible. A minimum of a 60-inch wide access aisle is required to be provided for every two accessible parking spaces. Accessible aisles were observed to be provided. The number of parking spaces provided meets accessibility requirements. The main entrance accessible ramp is located at the southwest side of the building. The accessible ramp generally met accessibility requirements.

The building contains accessible toilets.

Photographs



Accessible parking



Accessible restroom sign



Accessible restroom

Uniform Abbreviated Screening Checklist for the 2010 Americans with Disabilities Act			
	Item	Yes/ No	Comments
A.	History		
1.	Has an ADA Survey been completed for this property?	No	
2.	Have any ADA improvements been made to the property since original construction?	Yes	installation of accessible parking spaces, accessible ramp, and accessible toilet
3.	Has building ownership/management reported any ADA complaints or litigation?	N/A	
B.	Parking		
1.	Does the required number of standard ADA-designated spaces appear to be provided?	Yes	Four out of the 18 are accessible.
2.	Does the required number of van-accessible designated spaces appear to be provided?	Yes	Four van accessible spaces
3.	Are accessible spaces part of the shortest accessible route to an accessible building entrance?	Yes	
4.	Is a sign with the International Symbol of Accessibility at the head of each space?	Yes	Signs on the east spaces are not at the proper height.

Uniform Abbreviated Screening Checklist for the 2010 Americans with Disabilities Act			
	Item	Yes/ No	Comments
5.	Does each accessible space have an adjacent access aisle?	Yes	
6.	Do parking spaces and access aisles appear to be relatively level and without obstruction?	Yes	
C.	Exterior Accessible Route		
1.	Is an accessible route present from public transportation stops and municipal sidewalks in the property?	Yes	
2.	Are curb cut ramps present at transitions through curbs on an accessible route?	N/A	
3.	Do curb cut ramps appear to have the proper slope for all components?	N/A	
4.	Do ramps on an accessible route appear to have a compliant slope?	N/A	
5.	Do ramps on an accessible route appear to have a compliant length and width?	N/A	
6.	Do ramps on an accessible route appear to have a compliant end and intermediate landings?	N/A	
7.	Do ramps on an accessible route appear to have compliant handrails?	N/A	
D.	Building Entrances		
1.	Do a sufficient number of accessible entrances appear to be provided?	Yes	
2.	If the main entrance is not accessible, is an alternate accessible entrance provided?	N/A	
3.	Is signage provided indicating the location of alternate accessible entrances?	N/A	
4.	Do doors at accessible entrances appear to have compliant clear floor area on each side?	Yes	
5.	Do doors at accessible entrances appear to have compliant hardware?	No	Lever handles should be provided.
6.	Do doors at accessible entrances appear to have complaint opening width?	Yes	

Uniform Abbreviated Screening Checklist for the 2010 Americans with Disabilities Act			
	Item	Yes/ No	Comments
7.	Do pairs of accessible entrance doors in series appear to have the minimum clear space between them?	N/A	
8.	Do thresholds at accessible entrances appear to have compliant height?	Yes	
E.	Interior Accessible Routes and Amenities		
1.	Does an accessible route appear to connect with all public areas inside the building?	N/A	
2.	Do accessible routes appear free of obstructions and/or protruding objects?	Yes	
3.	Do ramps on accessible routes appear to have compliant slope?	Yes	
4.	Do ramps on accessible routes appear to have compliant length and width?	Yes	
5.	Do ramps on accessible routes appear to have compliant end and intermediate landings?	Yes	
6.	Do ramps on accessible routes appear to have compliant handrails?	Yes	
7.	Are adjoining public areas and areas of egress identified with accessible signage?	N/A	
8.	Do public transaction areas have an accessible, lowered counter section?	N/A	
9.	Do public telephones appear mounted with an accessible height and location?	N/A	
10.	Are publicly-accessible swimming pools equipped with an entrance lift?	N/A	
F.	Interior Doors		
1.	Do doors at interior accessible routes appear to have compliant clear floor area on each side?	Yes	
2.	Do doors at interior accessible routes appear to have compliant hardware?	Yes	

Uniform Abbreviated Screening Checklist for the 2010 Americans with Disabilities Act			
	Item	Yes/ No	Comments
3.	Do doors at interior accessible routes appear to have compliant opening force?	Yes	
4.	Do doors at interior accessible routes appear to have a compliant clear opening width?	Yes	
G.	Elevators		
1.	Are hallway call buttons configured with the "UP" button above the "DOWN" button?	N/A	
2.	Is accessible floor identification signage present on the hoistway sidewalls?	N/A	
3.	Do the elevators have audible and visual arrival indicators at the entrances?	N/A	
4.	Do the elevator hoistway and car interior appear to have a minimum compliant floor area?	N/A	
5.	Do the elevator car doors have automatic re-opening devices to prevent closure on obstructions?	N/A	
6.	Do elevator car control buttons appear to be mounted at a compliant height?	N/A	
7.	Are tactile and Braille characters mounted to the left of each elevator car control button?	N/A	
8.	Are audible and visual floor position indicators provided in the elevator car?	N/A	
9.	Is the emergency call system at the base of the control panel and not require voice communication?	N/A	
H.	Toilet Rooms		
1.	Do publicly-accessible toilet rooms appear to have a minimum compliant floor area?	Yes	
2.	Does the lavatory appear to be mounted at a compliant height and with compliant knee area?	Yes	
3.	Does the lavatory faucet have compliant handles?	Yes	

Uniform Abbreviated Screening Checklist for the 2010 Americans with Disabilities Act			
	Item	Yes/ No	Comments
4.	Is the plumbing piping under lavatories configured to protect against contact?	Yes	
5.	Are grab bars provided at compliant locations around the toilet?	Yes	Flush handle on toilet should be on the right side, away from wall.
6.	Do toilet stall doors appear to provide the minimum compliant clear width?	N/A	
7.	Do toilet stalls appear to provide the minimum compliant clear floor area?	N/A	
8.	Do urinals appear to be mounted at a compliant height and with compliant approach width?	Yes	
9.	Do accessories and mirrors appear to be mounted at a compliant height?	Yes	
I.	Hospitality Guestrooms		
1.	Does property management report the minimum required accessible guestrooms?	N/A	
2.	Does property management report the minimum required accessible guestrooms with roll-in showers?	N/A	

4.0 DOCUMENT REVIEW

4.1 DOCUMENTATION REVIEW

ECS requested relevant documentation from Josh Bontrager, to gain insight into the subject property's physical improvements, extent and type of use, and/or assist in identifying material discrepancies between reported information and observed conditions. ECS' review of documents submitted does not include commenting on the accuracy of such documents or their preparation, methodology, or protocol.

ECS was provided access to safety inspection records and previous reports.

4.2 INTERVIEW SUMMARY

ECS was escorted through the property by Josh Bontrager and Chris Woods who provided information about the property.

4.3 BUILDING, LIFE SAFETY, AND ZONING COMPLIANCE

ECS researched FOIA data using online property data and/or contacted the local building code compliance offices for the local jurisdiction. Initial research did not indicate outstanding building, life safety, or zoning violations. Upon receiving information regarding the status of the inquiries submitted, this report can be updated if necessary.

5.0 ADDITIONAL CONSIDERATIONS

5.1 MOISTURE AND MOLD

Comments

If present, evidence of mold and moisture issues are noted in the interior section of the report.

6.0 RECOMMENDATIONS AND OPINIONS OF COST

The opinion of cost are based upon approximate quantities, costs, and published information, and they include labor, material, design fees, and appropriate overhead, general conditions, and profit. A detailed analysis of quantities for cost estimating purposes is not included. The opinion of cost to repair, replace, or upgrade the improvements are considered typical for the marketplace. No contractors have provided pricing. The actual cost of repairs may vary from our opinions. ECS has not included contingency funds in our opinions. Amounts indicated represent today's dollars. ECS offers the following comments relative to Immediate and Capital Reserves criteria:

Immediate Issues

Physical deficiencies that require immediate action as a result of (i) existing or potentially unsafe conditions, (ii) significant negative conditions impacting tenancy, (iii) material building code violations, (iv) poor or deteriorated condition of critical element or system, or (v) a condition that is left "as is," with an extensive delay in addressing same, would result in or contribute to critical element or system failure within one year.

ECS has also included physical deficiencies inclusive of deferred maintenance that may not warrant immediate attention, but requiring repairs or replacements that should be undertaken on a priority basis, taking precedence over routine preventative maintenance work within a zero to one year time frame. Included are such physical deficiencies resulting from improper design, faulty installation, and/or substandard quality of original systems or materials. Components or systems that have realized or exceeded their Expected Useful Life (EUL) that may require replacement to be implemented within a zero to one year time frame are also included.

Capital Reserves

Capital Reserves are for recurring probable expenditures, which are not classified as operational or maintenance expenses, which should be annually budgeted for in advance. Capital reserves are reasonably predictable both in terms of frequency and cost. However, they may also include components or systems that have an indeterminable life but nonetheless have a potential liability for failure within an estimated time period. A component method has also been included within this report as well.

Capital Reserves excludes systems or components that are estimated to expire after the reserve term and that are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that were not deemed to have a material affect on the use were also excluded. Costs that are caused by acts of God, accidents or other occurrences that are typically covered by insurance, rather than reserved funds, are also excluded.

Replacement costs were solicited from ownership/property management, ECS' discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by ownership's or property management's maintenance staff were also considered.

ECS's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the evaluation period. Additional information concerning systems or components respective replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Capital Reserve Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined in the Immediate Needs Cost Estimates.

7.0 FACILITY CONDITION INDEX (FCI)

In accordance with our proposal add alternate, ECS determined the Facility Condition Index (FCI) value for the Preston Morris Building building. ECS determined the FCI value in accordance with industry standards and methodology sponsored by The National Association of College and University Business Officers (NACUBO). The FCI calculation methodology consists of dividing the total cost of Maintenance, Repair, and Replacement Deficiencies of the Facility by the Current Replacement Value of the Facility. FCI values and condition of the buildings based on the industry accepted interpretation of FCI values with ratings: good (under 0.05), fair (0.05 to 0.10), and poor (over 0.10).

Based on our Facility Condition Assessment, the total repair and replacement costs for the Preston Morris Building building is \$58,500. The replacement construction cost value obtained from the RS MEANS square foot estimator application is \$602,823. Please see attached documentation from RS MEANS program output as an appendix to the report. The calculated FCI value is determined to be 0.10. In accordance with the industry standards and methodology sponsored by The National Association of College and University Business Officers (NACUBO), the condition of Preston Morris Building is rated as fair.

Appendix I: SITE MAP AND AERIAL PHOTOGRAPH



Untitled Map





Untitled Map



Appendix II: FIRE EXTINGUISHER INSPECTION

Inspection Certificate

For

City of Charlottesville -Preston
Morris Bldg
407 East High Street
Charlottesville, VA 22903

This Inspection was performed in accordance with applicable Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.


*Inspection Date
Jun 10, 2021*

Building: City of Charlottesville -Preston Morris Bldg
Contact: Jason Davis
Title: Maintenance Tech

Company: Fire Solutions
Contact: Tommy VO
Title: Technician

Executive Summary

Generated by: BuildingReports.com

Building Information								
Building: City of Charlottesville -Preston Morris Bldg			Contact: Jason Davis					
Address: 407 East High Street			Phone: 434-964-6771					
Address:			Fax:					
City/State/Zip: Charlottesville, VA 22903			Mobile:					
Country: United States of America			Email: davisja@charlottesville.org					
Inspection Performed By								
Company: Fire Solutions			Inspector: Tommy VO					
Address: 205 Haley Road			Phone: 804-385-3301					
Address:			Fax:					
City/State/Zip: Ashland, Virginia 23005			Mobile: 804-385-3301					
Country: United States			Email: tommyv@firesolutionsinc.com					
Inspection Summary								
Category:	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Fire	3	100.00%	3	100.00%	3	100.00%	0	0%
Totals	3	100%	3	100.00%	3	100.00%	0	0%
Verification								
<div><div>Company: Fire Solutions</div><div>Inspector: Tommy VO</div><div>Building: City of Charlottesville -Preston Morris Bldg</div><div>Contact: Jason Davis</div></div>								
Fire Solutions Certifications								
Certification Type						Number		
WBENC Certified						2005121836		

Inspection & Testing

Generated by: BuildingReports.com

Building: City of Charlottesville -Preston Morris Bldg

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed /Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	ScanID : S/N	Service	Date Time
<i>Passed</i>				
Fire				
Fire Extinguisher, 5 Lbs, A.B.C.	Basement mechanical room 149.01	49753003 AW962217	Inspected	06/10/21 9:28:54 AM
Fire Extinguisher, 5 Lbs, A.B.C.	1st stairwell 149.02	52889962 XF-108369	Inspected	06/10/21 9:28:06 AM
Fire Extinguisher, 10 Lbs, A.B.C.	2nd hallway 149.03	49753002 XY388293	Inspected	06/10/21 9:29:27 AM

Service Summary

Generated by: BuildingReports.com

Building: City of Charlottesville -Preston Morris Bldg		
<i>The Service Summary section provides an overview of the services performed in this report.</i>		
Device Type	Service	Quantity
<i>Passed</i>		
Fire Extinguisher, 10 Lbs, A.B.C.	Inspected	1
Fire Extinguisher, 5 Lbs, A.B.C.	Inspected	2
Total		3
Grand Total		3

Fire Extinguisher Maintenance Report

Generated by: BuildingReports.com

Building: City of Charlottesville -Preston Morris Bldg					
<i>This report provides details on the Hydrostatic Test and Maintenance/Breakdown dates for fire extinguishers. Items that will need either of these services at any time in the next two years are displayed. Items are grouped together by year for budgeting purposes.</i>					
ScanID	Location	Serial #	Hydro	Breakdown	Mfr Date
Due in 2023					
Breakdown/Maintenance					
Fire Extinguisher, A.B.C., 5 Lbs					
52889962	1st stairwell 149.02	XF-108369	05/15/17	05/15/17	05/15/05
Total Fire Extinguisher, A.B.C., 5 Lbs:					1

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: City of Charlottesville -Preston Morris Bldg

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type		Category		% of Inventory	Quantity
Fire Extinguisher		Fire		100.00%	3
Type	Qty	Model #	Description	Manufacture Date	
In Service - 5 Years to 10 Years					
Amerex					
Fire Extinguisher	1	AB500-12	A.B.C.	08/07/2012	
In Service - 15 Years to 25 Years					
Amerex					
Fire Extinguisher	1	AB456-06	A.B.C.	05/15/2006	
Badger					
Fire Extinguisher	1	B5M-05	A.B.C.	05/15/2005	

Appendix III: RS MEANS ESTIMATE FOR FACILITY CONDITION INDEX (FCI)

Square Foot Cost Estimate Report

Date: 11/2/2021

Estimate Name	Preston Morris Building
	City of Charlottesville 407 East High Street Charlottesville Charlottesville 22902
Building Type	Office, 2-4 Story (Green) with Brick Veneer / Wood Frame
Location	CHARLOTTESVILLE, VA
	2.00
Stories Height	10.00
Floor Area (S.F.)	2,766.00
LaborType	OPN
Basement Included	Yes
Data Release	Year 2021
Cost Per Square Foot	\$217.94
Total Building Cost	\$602,823.42



Costs are derived from a building model with basic components.
 Scope differences and market conditions can cause costs to vary significantly.

**** Area entered is outside the range recommended by RSMeans.**

Assembly Customization Type :

- ☒ Added
- ☐ Partially Swapped
- ☐ Fully Swapped

		Quantity	% of Total	Cost Per SF	Cost
A Substructure			5.6%	\$9.06	\$25,051.69
A1010	Standard Foundations			\$5.24	\$14,484.74
	Strip footing, concrete, reinforced, load 11.1 KLF, soil bearing capacity 6 KSF, 12" deep x 24" wide	150.00		\$1.96	\$5,430.45
	Spread footings, 3000 PSI concrete, load 200K, soil bearing capacity 6 KSF, 6' - 0" square x 20" deep	11.98		\$3.27	\$9,054.29
A1030	Slab on Grade			\$2.54	\$7,031.89
	Slab on grade, 4" thick, non industrial, reinforced, recycled plastic vapor barrier	1,383.00		\$2.54	\$7,031.89
A2010	Basement Excavation			\$1.28	\$3,535.06

		Quantity	% of Total	Cost Per SF	Cost
	Excavate and fill, 10,000 SF, 8' deep, sand, gravel, or common earth, on site storage	1,383.00		\$1.28	\$3,535.06
B Shell			28.2%	\$45.87	\$126,879.80
B1010	Floor Construction			\$12.83	\$35,493.73
	Cast-in-place concrete column, 12" square, tied, 200K load, 12' story height, 142 lbs/LF, 4000PSI	143.81		\$3.39	\$9,362.94
	Flat slab, concrete, with drop panels, 6" slab/2.5" panel, 12" column, 15'x15' bay, 75 PSF superimposed load, 153 PSF total load	1,383.00		\$6.46	\$17,877.42
B1020	Roof Construction				
	Floor, wood joist, 2 x 12 @12" O.C., 1/2" CDX subfloor	1,383.00		\$2.98	\$8,253.37
	Wood roof, flat rafter, 2" x 12", 16" O.C.	1,383.00		\$2.60	\$7,189.75
B2010	Exterior Walls			\$17.47	\$48,326.76
	Brick veneer wall, standard face, 2x6 studs @ 16" back-up, running bond	2,400.00		\$17.47	\$48,326.76
B2020	Exterior Windows			\$6.60	\$18,253.51
	Windows, aluminum, awning, insulated glass, 4'-5" x 5'-3"	26.09		\$6.60	\$18,253.51
B2030	Exterior Doors			\$1.28	\$3,527.27
	Door, aluminum & glass, with transom, narrow stile, double door, hardware, 6'-0" x 10'-0" opening	0.28		\$0.67	\$1,842.32
	Door, aluminum & glass, with transom, bronze finish, hardware, 3'-0" x 10'-0" opening	0.28		\$0.34	\$930.24
	Door, steel 18 gauge, hollow metal, 1 door with frame, no label, 3'-0" x 7'-0" opening, low VOC paint	0.28		\$0.27	\$754.71
B3010	Roof Coverings			\$5.09	\$14,088.78
	Roofing, single ply membrane, TPO, 60 mil membrane, heat welded seams, fully adhered	1,383.00		\$0.86	\$2,377.32
	Insulation, rigid, roof deck, extruded polystyrene, 40 PSI compressive strength, 4" thick, R20	1,383.00		\$1.98	\$5,479.83
	Roof edges, aluminum, duranodic, .050" thick, 6" face	150.00		\$1.36	\$3,773.97
	Flashing, aluminum, no backing sides, .019"	150.00		\$0.22	\$620.01
	Gravel stop, aluminum, extruded, 4", duranodic, .050" thick	150.00		\$0.66	\$1,837.64
C Interiors			13.8%	\$22.45	\$62,098.05
C1010	Partitions			\$4.05	\$11,209.66
	Wood partition, 5/8" fire rated gypsum board face, no base layer, 2x4, @ 16", 5/8" reg gypsum board opposite face, 0 insul	1,106.40		\$1.38	\$3,825.53
	1/2" fire rated gypsum board, taped & finished, painted on metal furring, low VOC paint	2,400.00		\$2.67	\$7,384.13

		Quantity	% of Total	Cost Per SF	Cost
C1020	Interior Doors			\$5.42	\$14,989.44
	Door, single leaf, kd steel frame, hollow metal, commercial quality, flush, 3'-0" x 7'-0" x 1-3/8", low VOC paint	13.83		\$5.42	\$14,989.44
C1030	Fittings			\$1.29	\$3,566.17
	Toilet partitions, cubicles, ceiling hung, stainless steel	3.32		\$1.29	\$3,566.17
C2010	Stair Construction			\$1.18	\$3,274.13
	Stairs, wood, prefab box type, oak treads, wood rails 3'-6" wide, 14 risers	1.38		\$1.18	\$3,274.13
C3010	Wall Finishes			\$1.03	\$2,852.41
	Vinyl wall covering, fabric back, medium weight	1,327.68		\$0.87	\$2,409.62
	Painting, interior on plaster and drywall, walls & ceilings, roller work, primer & 2 coats, low VOC	885.12		\$0.16	\$442.79
C3020	Floor Finishes			\$4.24	\$11,739.20
	Carpet tile, nylon, fusion bonded, 18" x 18" or 24" x 24", 24 oz	1,659.60		\$2.46	\$6,799.20
	Tile, ceramic natural clay	276.60		\$0.86	\$2,384.89
	Vinyl, composition tile, 12" x 12" x 1/8" thick, recycled content	829.80		\$0.92	\$2,555.11
C3030	Ceiling Finishes			\$5.23	\$14,467.04
	Acoustic ceilings, 3/4" mineral fiber, 12" x 12" tile, concealed 2" bar & channel grid, suspended support	2,766.00		\$5.23	\$14,467.04
D Services			52.4%	\$85.34	\$236,060.11
D1010	Elevators and Lifts			\$11.31	\$31,281.08
	Hydraulic passenger elevator, 3000 lb, 3 floors, 12' story height, 2 car group, 125 FPM	0.28		\$11.31	\$31,281.08
D2010	Plumbing Fixtures			\$4.44	\$12,269.83
	Water closet, vitreous china, bowl only w/ auto flush sensor flush valve, wall hung, 1.28 gpf	1.33		\$1.69	\$4,661.92
	Urinal, vitreous china, wall hung, waterless, ADA	0.66		\$0.15	\$402.83
	Lavatory w/trim, vanity top, PE on CI, 20" x 18", faucet w/ hydroelectric powered motion sensor	1.33		\$1.09	\$3,009.88
	Service sink w/trim, PE on CI, wall hung w/rim guard, 24" x 20"	0.66		\$1.04	\$2,885.66
	Water cooler, electric, wall hung, wheelchair type, 7.5 GPH, GreenSpec certified, ADA	0.71		\$0.47	\$1,309.53
D2020	Domestic Water Distribution			\$0.20	\$547.15
	Gas fired water heater, commercial, 100< F rise, tankless, on-demand, natural gas/propane, 8.4 GPM	0.14		\$0.20	\$547.15
D2040	Rain Water Drainage			\$0.71	\$1,962.35
	Roof drain, CI, soil, single hub, 4" diam, 10' high	0.55		\$0.40	\$1,098.35

		Quantity	% of Total	Cost Per SF	Cost
	Roof drain, CI, soil, single hub, 4" diam, for each additional foot add	20.19		\$0.31	\$864.00
D3040	Distribution Systems			\$2.77	\$7,663.87
	Heat recovery pkgs, air to air, enthalpy recovery wheel, 10000 max CFM	0.41		\$2.77	\$7,663.87
D3050	Terminal & Package Units			\$13.92	\$38,490.41
	Rooftop, multizone, air conditioner, green offices, 25,000 SF, 50 ton SEER 14	2,766.00		\$13.92	\$38,490.41
D4010	Sprinklers			\$3.28	\$9,076.15
	Wet pipe sprinkler systems, steel, light hazard, 1 floor, 5000 SF	940.44		\$1.41	\$3,899.51
	Wet pipe sprinkler systems, steel, light hazard, each additional floor, 5000 SF	1,825.56		\$1.61	\$4,456.81
	Standard High Rise Accessory Package 3 story	0.14		\$0.26	\$719.83
D4020	Standpipes			\$1.06	\$2,926.02
	Wet standpipe risers, class III, steel, black, sch 40, 4" diam pipe, 1 floor	0.17		\$0.58	\$1,599.17
	Wet standpipe risers, class III, steel, black, sch 40, 4" diam pipe, additional floors	0.62		\$0.48	\$1,326.85
D5010	Electrical Service/Distribution			\$17.77	\$49,156.94
	Overhead service installation, includes breakers, metering, 20' conduit & wire, 3 phase, 4 wire, 120/208 V, 800 A	1.25		\$4.59	\$12,698.44
	Feeder installation 600 V, including RGS conduit and XHHW wire, 800 A	100.00		\$5.66	\$15,644.50
	Switchgear installation, incl switchboard, panels & circuit breaker, 120/208 V, 3 phase, 800 A	1.20		\$7.52	\$20,814.00
D5020	Lighting and Branch Wiring			\$13.41	\$37,091.30
	Receptacles incl plate, box, conduit, wire, 16.5 per 1000 SF, 2.0 W per SF, with transformer	2,766.00		\$3.49	\$9,659.15
	Miscellaneous power, 1.2 watts	2,766.00		\$0.25	\$688.18
	Central air conditioning power, 3 watts	2,766.00		\$0.46	\$1,263.23
	Motor installation, three phase, 460 V, 15 HP motor size	2.00		\$1.34	\$3,714.50
	LED fixtures recess mounted in ceiling, 0.69 watt per SF	3,180.90		\$5.50	\$15,199.61
	Daylight dimming control system, 5 fixtures per 1000 SF	1,383.00		\$0.63	\$1,754.06
	Lighting on/off control system, 5 fixtures per 1000 SF	2,766.00		\$0.82	\$2,254.57
	Lighting on/off control system, 10 fixtures per 1000 SF	2,766.00		\$0.92	\$2,558.00
D5030	Communications and Security			\$7.15	\$19,781.50
	Telephone wiring for offices & laboratories, 8 jacks/MSF (cost per MSF)	2.07		\$1.17	\$3,240.89

		Quantity	% of Total	Cost Per SF	Cost
	Communication and alarm systems, fire detection, non-addressable, 100 detectors, includes outlets, boxes, conduit and wire	0.14		\$2.52	\$6,977.79
	Communication and alarm systems, fire detection, addressable, 50 detectors, includes outlets, boxes, conduit and wire	0.14		\$1.60	\$4,436.94
	Fire alarm command center, addressable with voice, excl. wire & conduit	0.14		\$0.59	\$1,625.16
	Internet wiring, 8 data/voice outlets per 1000 S.F.	2.07		\$1.27	\$3,500.72
D5090	Other Electrical Systems			\$9.33	\$25,813.51
	Generator sets, w/battery, charger, muffler and transfer switch, gas/gasoline operated, 3 phase, 4 wire, 277/480 V, 7.5 kW	0.12		\$0.05	\$148.01
	Uninterruptible power supply with standard battery pack, 15 kVA/12.75 kW	0.28		\$0.00	\$0.30
	Energy monitoring systems, electrical, three phase, 5 meters	0.50		\$3.40	\$9,409.00
	Energy monitoring systems, mechanical, BTU, 3 meters w/3 duct & 3 space sensors	1.00		\$4.15	\$11,477.25
	Energy monitoring systems, Front end display	3.00		\$0.68	\$1,869.45
	Energy monitoring systems, Computer workstation	1.00		\$1.05	\$2,909.50
E Equipment & Furnishin			0.1%	\$0.22	\$619.46
E1090	Other Equipment			\$0.21	\$580.83
	Waste handling, recycling, tilt truck, plastic, with wheels, 0.5 C.Y., 850 lb capacity	0.14		\$0.21	\$580.83
E2020	Moveable Furnishings			\$0.01	\$38.63
	Signage, exterior, surface mounted, 24 ga aluminum, 10" x 7", no smoking	0.83		\$0.01	\$38.63
F Special Construction			0.0%	\$0.00	\$0.00
G Building Sitework			0.0%	\$0.00	\$0.00
Sub Total			100%	\$162.95	\$450,709.10
Contractor's Overhead & Profit			25.0 %	\$40.74	\$112,677.28
Architectural Fees			7.0 %	\$14.26	\$39,437.05
User Fees			0.0 %	\$0.00	\$0.00
Total Building Cost				\$217.94	\$602,823.42

Appendix IV: SITE PHOTOGRAPHS



1 - Preston Morris Building



2 - Brick ramp at southwest side of the building



3 - Brick sidewalk south side of the building



4 - Cracked brick sidewalk at south side of building



5 - Brick work retaining wall condition



6 - Brick ramp at southwest side of the building



7 - Signage of the property



8 - Landscape area



9 - Building mounted light



10 - Building exterior north side of the building - note downspout condition



11 - Downspout in south side of building



12 - Structural framing



13 - Structural framing



14 - Building exterior southeast side of the building



15 - Building exterior north side of the building



16 - Building exterior southeast side of the building



17 - Exterior wall condition on west side of building



18 - Building exterior northwest side of the building



19 - Main entrance door



20 - Building exterior north side of the building - note deterioration



21 - Typical exterior window



22 - Typical exterior window



23 - Typical exterior window condition



24 - Electric domestic water heater



25 - Condenser Unit



26 - Condenser Unit



27 - Condenser Unit



28 - Air Handler Unit



29 - Air Handler Unit



30 - Typical thermostat control



31 - Typical thermostat control



32 - Typical mechanical duct



33 - Digital electric meter



34 - Main electrical disconnect



35 - Electrical panel



36 - Typical circuit breaker panel manufactured by Square D



37 - Fire hydrant



38 - Fire extinguisher



39 - Typical exit sign



40 - Interior finishes entrance area



41 - Accessible restroom



42 - Typical meeting room




43 - Typical office interior



44 - Typical corridor interior



45 - Typical handrail stair



46 - Typical stair



47 - Typical restroom interior



48 - Typical men's restroom



49 - Typical men's restroom



50 - Accessible parking



51 - Accessible brick ramp at southwest side of the building



52 - Accessible restroom sign



53 - Accessible restroom

Appendix V: RESUMES

Michael G. Doyle, AIA

Principal Architect – Facilities Department

EDUCATION

Bachelor of Architecture, 1987, Architecture, Virginia Polytechnic Institute and State University, Blacksburg, VA

REGISTRATIONS

Registered Architect: AZ, DC, MD, VA, NC, IL
The Leadership in Energy and Environmental Design (LEED) Accredited Professional: 2009

Mr. Doyle serves as a Principal Architect for the Facilities Engineering Group in ECS Chantilly. He has over 25 years of experience in the construction industry, and his expertise includes the Americans with Disabilities Act, Property Condition Surveys, Pre and Post Construction Survey Services, Pavement Assessments, and Third-Party Plan Review. He has worked with numerous government agencies and has significant experience with local government and educational facilities; commercial high-rise buildings; multi-unit, residential, and correctional facilities. Mr. Doyle also has had experience on several high-profile historic projects, including the Jefferson Memorial, the Tivoli Theater, the Tariff Building, The White House, the Court of Appeals in Washington, DC; the Valley Bank Building in Leesburg, Virginia; and the Shenandoah Courthouse at Woodstock, Virginia.

Property Condition Assessments - Mr. Doyle has extensive experience performing property condition assessments from small commercial properties, large high rise buildings, to government-owned properties. Mr. Doyle has performed assessment in general accordance with ASTM E 2018, Standard Guide for Property Condition Assessments: Baseline Property Condition Assessment Process. Mr. Doyle also has experience in performing property condition assessments in accordance with lender and specific client requirements. Mr. Doyle has worked with teams of experts in providing detailed reports and simple reserve analysis for properties.

RELEVANT PROJECT EXPERIENCE

Darien Lake, Darien Center, NY – Mr. Doyle was the Principal Architect for the property assessment of the Darien Lake amusement park. The property included over 200 buildings including buildings within the park, maintenance and administration buildings, hotel, campground buildings, and sewer treatment center.

Ballston Park Apartments, Arlington, VA (2014) - originally developed in 1938, this complex includes 50 two-story apartment buildings, one three-story apartment building, one single-family residence, and a single-story office/clubhouse. A PCA and a Phase I Environmental Site Assessment was conducted and documented.

Hyatt House Lodging, Sterling, VA (2014) - This six-story, 162-room, 98,793-square-foot hotel with surface parking was constructed in 2007 as a Sierra Suites and subsequently converted to a Hyatt House. Recreational facilities include a swimming pool, fitness center, a grill area, and a fire pit. Building systems observed per ASTM E 2018 included site conditions, the structural frame and building envelope; plumbing, mechanical and electrical systems, vertical transportation Systems, life safety and fire protection, and ADA Considerations. A Phase I Environmental Site Assessment was also conducted.

WHMO Facilities Assessment, Washington, DC (2015) - This is a privately owned, government-leased facility with a sensitive mission. The structure is believed to be a 1920s vintage building designed as a multi-story car dealership. The government has occupied this space continuously since 1963. Mr. Doyle conducted a survey of the complete facility, identified and documented areas of concerns. He also provide a recommendation for remediation for each area of concern, a Rough Order Magnitude (ROM) cost for remediation, and categorized each area of concern as critical, non-critical or aesthetic.

ADDITIONAL PROJECT EXPERIENCE

- City of Charlottesville Portfolio, Charlottesville, VA
- Liberty Park, Herndon, VA
- Oakcrest School, McLean, VA
- Signature Flight Support, Arlington, VA
- The Gap, Washington, DC
- Lanham Crossing, Lanham, MD
- ZIM American Headquarters Building, Suffolk, VA
- The Portrait Building, Washington, DC
- The Aventine of Alexandria, Alexandria, VA



DONALD GOGLIO

CODE COMPLIANCE PROJECT MANAGER



CERTIFICATIONS

Master Plumber
Master Gasfitter
Cross Connection Technician
Commercial Building Inspector
Commercial Plumbing Inspector
Commercial Mechanical Inspector
Accessibility Inspector/Plan
Reviewer
Fire Inspector I and II
LEED Green Associate
CPR/First Aid Training
OSHA 30 hr Training

SKILLS

Code Compliance
Construction Administration
Special Inspection Services
Condition Assessments
Forensic Consultation

PROFESSIONAL MEMBERSHIPS

American Wood Council
USGBC

EDUCATION

Montgomery College, 1991
Silver Spring, MD

YEARS OF EXPERIENCE

ECS: <1 Other: 38

PROFESSIONAL PROFILE

Mr. Goglio has 38 years of construction, mechanical trade, and management experience. He manages code compliance projects, including reviewing plans, providing technical support, and conducting inspections.

PROJECT EXPERIENCE

Fort Lee AIT Barracks, Ft. Lee, VA – Quality Control Manager – The Fort Lee AIT Barracks project is a soldiers' basic combat training facility for over 1,200 Army personnel. The complex is a cohesive development, providing both housing and affiliated functions for soldiers in the AIT program. In addition to housing, the facility includes an outdoor jogging track, physical training pits, and access drivers and parking areas that meet USACE requirements. The project's five-story brick buildings meet DoD Minimum Antiterrorism Standards for Buildings and obtained LEED® Gold certification from the US Green Building Council. The Fort Lee project is part of the Northeast Region Multiple Award Task Order Contract (MATOC).

Terrapin Row, College Park, MD – Assistant Superintendent – Terrapin Row is a transformative student housing complex located on the University of Maryland's historic South Campus. The mixed-use community features 1,493 beds across 418 apartments as well as a 489-space parking garage. Terrapin Row boasts ample amenities centered around a college lifestyle, including a swimming pool, volleyball court, outdoor kitchens and fire pits, exterior TVs, a fitness center, bike storage, a cyber cafe and game room, and numerous live-learn spaces. The multi-phase project consists of seven buildings and encompasses a pedestrian and bike-friendly Village Green surrounded by over 11,856 square feet of retail space. The Village Green flows into a grand stairway and amphitheater that opens to a pedestrian plaza to welcome pedestrians towards the main academic centers of campus.

The Hartley at the Parks, Washington, DC – Assistant Superintendent – The Hartley is a 323-unit mixed-use apartment community with a Whole Foods Market as its retail anchor in Northwest DC. This six-story community consists of five stories of wood framing over a one-story concrete podium with 317 apartments and six townhomes. It is a part of The Parks at Walter Reed, a mixed-use master-planned redevelopment of the 66-acre historic Walter Reed Army Medical Center with 2,200 residential units plus office and retail. The Hartley features two interior courtyards: the north courtyard includes pool and amenity space, and the south courtyard includes a Zen Garden. The second-floor amenity space includes a lounge, multi-purpose room, fitness center, and pet spa. The studio, one-, two-, and three-bedroom units feature high-end finishes, including quartz countertops and EnergyStar® appliances.



DONALD GOGLIO

CODE COMPLIANCE PROJECT MANAGER



CERTIFICATIONS

Master Plumber
Master Gasfitter
Cross Connection Technician
Commercial Building Inspector
Commercial Plumbing Inspector
Commercial Mechanical Inspector
Accessibility Inspector/Plan
Reviewer
Fire Inspector I and II
LEED Green Associate
CPR/First Aid Training
OSHA 30 hr Training

SKILLS

Code Compliance
Construction Administration
Special Inspection Services
Condition Assessments
Forensic Consultation

PROFESSIONAL MEMBERSHIPS

American Wood Council
USGBC

EDUCATION

Montgomery College, 1991
Silver Spring, MD

YEARS OF EXPERIENCE

ECS: <1 Other: 38

PROFESSIONAL PROFILE

Mr. Goglio has 38 years of construction, mechanical trade, and management experience. He manages code compliance projects, including reviewing plans, providing technical support, and conducting inspections.

PROJECT EXPERIENCE

- Fort Lee AIT Barracks, Ft. Lee, VA
- Terrapin Row, College Park, MD
- The Hartley at the Parks, Washington, DC
- River Point, Washington, DC
- Juniper, Columbia, MD
- The Smith, King of Prussia, PA
- Banner Hill, Baltimore, MD
- Jefferson Square, Baltimore, MD
- Metropolitan at Largo Station, Largo, MD
- The Village at Leesburg, Leesburg, VA
- The Elms at Clarksburg Village, Clarksburg, MD
- Hidden Creek, Gaithersburg, MD
- Paramount, Gaithersburg, MD
- Thayer & Spring, Silver Spring, MD





William R. Pratt, PE

Principal Engineer, ECS Mid-Atlantic, LLC
Professional-In-Charge

EDUCATION

Bachelor of Science, 1989, Mechanical Engineering, University of Massachusetts

REGISTRATIONS

Professional Engineer: DC, VA, MD

ICC Commercial Building, Plumbing, and Mechanical Inspector

Mr. Pratt serves as Senior Project Engineer for ECS Mid-Atlantic, LLC. Mr. Pratt is responsible as the Professional-In-Charge of the code compliance group and provides supervision of code compliance inspection programs for the local jurisdictions. Additionally, he oversees execution of project management for construction materials testing, property condition assessments.

PROPERTY CONDITION ASSESSMENTS - Bill has extensive experience in performing property condition assessments for a variety of properties and structures. These assessments include evaluation of site improvements, building components, roofing, pavements, electrical systems, mechanical systems, and HVAC systems. He performs assessment in general accordance with ASTM E 2018 – 08, Standard Guide for Property Condition Assessments: Baseline Property Condition Assessment Process. Bill also has experience in performing property condition assessments that meet with lender and specific client requirements. He works with teams of experts in providing detailed reports and simple reserve analysis for properties.

SELECT PROJECT EXPERIENCE – PCA

- City of Charlottesville, VA - 51 Property
- Portfolio including schools, libraries, museums, fire and police stations, and court buildings
- Home Properties 800+ Apartment Units, 4-Property Portfolio to Freddie Mac Standard, Hampton and Virginia Beach, VA
- Boulders Office Park 300,000+ SF, 3-Property Portfolio, Richmond, VA
- Darien Lake Theme Park, Darien Center, NY
- Madison Place Office Building, Alexandria, VA
- King of Glory Lutheran Church, Williamsburg, VA
- Comfort Inn, Charlottesville, VA
- The Wisconsin Building, Washington, DC

SELECT PROJECT EXPERIENCE – CODE COMPLIANCE AND SPECIAL INSPECTIONS

- City Center DC, Washington, DC
- DC Courts Judiciary Square, IDIQ Contract, Washington, DC
- Hilton Garden Inn, Washington, DC
- Waterfront Mall, Washington, DC
- 4th Street Reconstruction, Washington, DC
- Sibley Memorial Hospital Addition, Cancer Center, Washington, DC
- Washington Headquarters Services, Arlington, VA
- Walmart #5968-00, Washington, DC
- Progression Place, 7th Street, NW, Washington, DC
- National Gallery of Art, Washington, DC
- City Market @ O, Washington, DC

