



VENABLE ELEMENTARY SCHOOL
406 14TH STREET NW
CHARLOTTESVILLE, VIRGINIA

ECS PROJECT NO. 46:6713

FOR

CITY OF CHARLOTTESVILLE - FACILITIES DEVELOPMENT

OCTOBER 28, 2021





October 28, 2021

Mr. Josh Bontrager
City of Charlottesville - Facilities Development
305 4th Street NW
Charlottesville, Virginia, 22903

ECS Project No. 46:6713

Reference: Facility Condition Assessment Report for Venable Elementary School, 406 14th Street NW, Charlottesville, Virginia

Dear Mr. Bontrager:

ECS Mid-Atlantic, LLC is pleased to provide the results of our Facility Condition Assessment (FCA) for the referenced property. The scope of the FCA was performed in general accordance with ASTM and industry guidelines and items contained within the ECS Proposal No. 46:7239-FP, dated June 12, 2020. We understand that our work is being performed under the City of Charlottesville Purchase Order Number 4500313133.

It has been our pleasure to be of service to you on this project. Should you have any questions or comments with regard to the findings and recommendations, please feel free to contact us at your convenience.

Respectfully,

ECS Mid-Atlantic, LLC

A handwritten signature in black ink, appearing to read 'D. Goglio'.

Donald M. Goglio
Project Manager
DGoglio@ecslimited.com
703-471-8400

A handwritten signature in blue ink, appearing to read 'Michael G. Doyle'.

Michael G. Doyle, AIA
Principal Architect
mdoyle@ecslimited.com
703-471-8400

Project Summary

Construction System	Good	Fair	Poor	Action	Immediate	Over Term Years 1-20
3.2.1 Topography	X			None		
3.2.2 Storm Water Drainage	X			None		
3.2.3 Access and Egress	X			None		
3.2.4 Paving, Curbing, and Parking	X	X		Repair		\$20,000
3.2.5 Flatwork		X		Replace		\$10,000
3.2.6 Landscaping and Appurtenances	X			None		
3.2.7 Recreational Facilities	X	X		Replace		\$55,000
3.2.8 Special Utility Systems		NA		None		
3.3.1 Foundation	X			None		
3.3.2 Building Frame	X			None		
3.3.3 Building Exteriors		X		Repair		\$300,000
3.3.4 Exterior Doors	X			None		
3.3.5 Exterior Windows	X	X		None		
3.3.6 Roofing Systems	X	X		Repair		\$20,000
3.4.1.1 Supply and Waste Piping	X			None		
3.4.1.2 Domestic Hot Water Production		X		Replace		\$2,400
3.4.2.1 Equipment	X	X		Replace		\$241,000
3.4.2.2 Distribution System	X			None		
3.4.2.3 Control Systems	X			None		
3.4.3.1 Service and Metering		X		Replace		\$30,000
3.4.3.2 Distribution	X			None		
3.5 VERTICAL TRANSPORTATION SYSTEMS	X			None		
3.6.1 Sprinklers and Suppression Systems	X			None		
3.6.2 Alarm Systems	X	X		Replace		\$30,000
3.6.3 Security and Other Systems	X			None		
3.7.1 Interior Finishes	X			Refurbish		\$75,000
3.8 Accessibility (ADA) Compliance	X	X		REMOVE PROTRUSIONS	\$18,000	
5.1 MOISTURE AND MOLD	X			None		
Totals					\$18,000	\$783,400

Summary	Today's Dollars	\$/Square Feet
Immediate Repairs	\$18,000	\$0.29

	Today's Dollars	\$/Square Feet	\$/Square Feet/Year
Replacement Reserves, today's dollars	\$783,400.00	\$12.69	\$0.63
Replacement Reserves, w/20, 2.5% escalation	\$918,333.46	\$14.88	\$0.74

TABLE OF CONTENTS		PAGE
1.0	EXECUTIVE SUMMARY	1
1.1	BACKGROUND	1
1.2	METHODOLOGY	1
1.3	PROPERTY DESCRIPTION	4
1.4	OPINIONS OF COST	5
1.5	COST TABLES	6
	Immediate Repair Cost	7
	Capital Reserve Schedule	8
2.0	PURPOSE AND SCOPE	10
2.1	SCOPE OF SERVICES	10
2.2	Deviations from Guide (ASTM E2018-15)	10
2.3	ASSESSMENT PROCEDURES	11
2.4	DEFINITIONS	11
	2.4.1 Partial List of ASTM Definitions	11
3.0	SYSTEM DESCRIPTION AND OBSERVATIONS	14
3.1	PROPERTY DESCRIPTION	14
	3.1.1 Property Location	14
	3.1.2 Construction History	14
	3.1.3 Current Property Improvements	14
3.2	SITE CONDITIONS	14
	3.2.1 Topography	14
	3.2.2 Storm Water Drainage	15
	3.2.3 Access and Egress	15
	3.2.4 Paving, Curbing, and Parking	16
	3.2.5 Flatwork	17
	3.2.6 Landscaping and Appurtenances	20
	3.2.7 Recreational Facilities	21
	3.2.8 Special Utility Systems	23
3.3	STRUCTURAL FRAME AND BUILDING EXTERIOR	24
	3.3.1 Foundation	24
	3.3.2 Building Frame	24



3.3.3	Building Exteriors	24
3.3.4	Exterior Doors	28
3.3.5	Exterior Windows	29
3.3.6	Roofing Systems	30
3.4	PLUMBING, MECHANICAL, AND ELECTRICAL SYSTEMS	33
3.4.1	Plumbing Systems	33
3.4.1.1	Supply and Waste Piping	33
3.4.1.2	Domestic Hot Water Production	33
3.4.2	HVAC Systems	34
3.4.2.1	Equipment	34
3.4.2.2	Distribution System	39
3.4.2.3	Control Systems	39
3.4.3	Electrical Systems	40
3.4.3.1	Service and Metering	40
3.4.3.2	Distribution	41
3.5	VERTICAL TRANSPORTATION SYSTEMS	42
3.6	LIFE SAFETY AND FIRE PROTECTION	43
3.6.1	Sprinklers and Suppression Systems	43
3.6.2	Alarm Systems	45
3.6.3	Security and Other Systems	47
3.7	INTERIOR BUILDING COMPONENTS	47
3.7.1	Interior Finishes	47
3.8	Accessibility (ADA) Compliance	52
4.0	DOCUMENT REVIEW	58
4.1	DOCUMENTATION REVIEW	58
4.2	INTERVIEW SUMMARY	58
5.0	ADDITIONAL CONSIDERATIONS	59
5.1	MOISTURE AND MOLD	59
6.0	RECOMMENDATIONS AND OPINIONS OF COST	60
7.0	FACILITY CONDITION INDEX (FCI)	62



TABLE OF APPENDICES

Appendix I: SITE MAP AND AERIAL PHOTOGRAPH

Appendix II: FIRE EXTINGUISHER INSPECTION

Appendix III: FIRE SPRINKLER INSPECTION

Appendix IV: RS MEANS ESTIMATE FOR FACILITY CONDITION INDEX (FCI)

Appendix V: SITE PHOTOGRAPHS

Appendix VI: RESUMES

1.0 EXECUTIVE SUMMARY

1.1 BACKGROUND

ECS Mid-Atlantic, LLC (ECS) performed a Facility Condition Assessment (FCA) in general conformance with ASTM guidelines and general scope items contained within the ECS Proposal 46:7239-FP dated June 12, 2020 for the Venable Elementary School property in Charlottesville, Virginia - hereinafter known as the Property.

The FCA was conducted by ECS in response to the authorization of our Proposal by Ms. Susan Dyer on November 23, 2020. The report was completed and reviewed by the following team members:

William R. Pratt, P.E.	Principal Engineer
	Phone: 703-471-8400
	E-mail: wpratt@ecslimited.com
Michael G. Doyle, AIA	Principal Architect
	Phone: 703-471-8400
	E-mail: mdoyle@ecslimited.com
Donald M. Goglio	Project Manager
	Phone: 703-471-8400
	E-mail: DGoglio@ecslimited.com

Reliance

This report is provided for the exclusive use of City of Charlottesville - Facilities Development. This report is not intended to be used or relied upon in connection with other projects or by other unidentified third parties. The use of this report by any undesignated third party or parties will be at such party's sole risk and ECS disclaims liability for any such third party use or reliance.

1.2 METHODOLOGY

ECS observations and historical property data provided by the owner were utilized to determine the effective age of the property components. Various factors including exposure to weather elements, system manufacturer quality, level of maintenance, and usage determine the effective age of property components. Depending on the impact of these various factors, the effective age of property components can reduce the Remaining Useful Life (RUL) of a property component. The general requirements of the owner to address facility needs were requested to be prioritized based on the RUL and type of property component. The following Priorities were established by the Owner as follows:

Priority 1: Immediately Critical Items (Year 0)

Items in this Priority category include physical deficiencies that require immediate action as a result of (i) existing or potentially unsafe conditions, (ii) significant negative conditions impacting tenancy, (iii) material building code violations or Title II American with Disabilities Act (ADA) items.

Priority 2: Critical Items (Year 0-1)

Items in this Priority category include physical deficiencies that require immediate action as a result of (i) poor or deteriorated condition of critical element or system, or (ii) a condition that is left “as is,” with an extensive delay in addressing same, would result in or contribute to critical element or system failure within one year.

Priority 3: Near Term Items (Years 2-5)

Items in this category include physical deficiencies that require near term action as a result of (i) poor or deteriorated condition of critical element or system, or (ii) a condition that is left “as is,” with an extensive delay in addressing same, would result in or contribute to critical element or system failure within two to five years.

Priority 4: Reserve Items (Years 5-20)

Items in this Priority category include Capital Reserves for recurring probable expenditures, which are not classified as operational or maintenance expenses, which should be annually budgeted for in advance. Capital reserves are reasonably predictable both in terms of frequency and cost. However, they may also include components or systems that have an indeterminable life but nonetheless have a potential liability for failure within an estimated time period. A component method has also been included within this report as well.

Reserve items excludes systems or components that are estimated to expire after the reserve term and that are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that were not deemed to have a material affect on the use were also excluded. Costs that are caused by acts of God, accidents or other occurrences that are typically covered by insurance, rather than reserved funds, are also excluded.

Replacement costs were solicited from ownership/property management, ECS’ discussions with service companies, manufacturers’ representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by ownership’s or property management’s maintenance staff were also considered.

ECS’s reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the evaluation period. Additional information concerning systems or components respective replacement costs (in today’s dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Capital Reserve Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined in the Immediate Needs Cost Estimates.

1.3 PROPERTY DESCRIPTION

Venable Elementary School, located at 406 14th Street NW, in Charlottesville, Virginia, consists of a Two-story building and an Annex building. The building totals approximately 61,720 square feet. Parking is provided with At-grade parking with asphalt pavement. The School building was reportedly constructed in 1925.

SURVEY INFORMATION	
Date of Assessment	June 17, 2021
Assessor	William R. Pratt, P.E.
Weather Conditions	Sunny 78
Property Contact	Josh Bontrager, Project Manager for the City of Charlottesville - Facilities Development

SITE INFORMATION	
Land Area	2.70 acres
Major Cross Streets	Gordon Avenue
Pavement - Parking	At-grade parking with asphalt pavement
Number of Parking Spaces	51
Number of Accessible Spaces	Three
Number of Van Accessible Spaces	Three
Pedestrian Sidewalks	Concrete and brick pavers

BUILDING INFORMATION	
Building Type	School
Number of Buildings	Two
Building Height	Two-story
Square Footage	61,720
Year Constructed	1925
Year Remodeled	1990

BUILDING CONSTRUCTION	
Foundation	Assumed shallow spread footings
Structural System	Masonry bearing walls with wood framed roofing
Roof	Slate shingle
Exterior Finishes	Brick veneer
Windows	Aluminum frame single pane - operable, aluminum frame single pane
Entrance	Wood doors with glass

BUILDING SYSTEMS	
HVAC System	Central plant HVAC system with supplemental heating/cooling equipment
Domestic Hot Water	Gas domestic water heater
Water Distribution	Copper
Sanitary Waste Line	PVC and cast iron
Electrical Service	3-phase, 4-wire, 2,000 amps
Branch Wiring	Copper
Elevators	One passenger elevator
Fire Suppression System	Wet sprinkler system and fire extinguishers with automated fire alarm system with alarm bell, strobe, and pull down stations

UTILITY SERVICE PROVIDERS	
Water	Charlottesville Water
Sewer	Charlottesville Public Utilities - Wastewater
Electric	Dominion Virginia Power
Natural Gas	City of Charlottesville

1.4 OPINIONS OF COST

The opinions of cost are provided in the attached reserve replacement table and a summary of immediate repairs included in this report. The reserve replacement table covers capital expenditure items only. Items less than \$1,000 in cost have been excluded, except for immediate repairs, ADA or safety issues. Please refer to section 6.0 of this report for a detailed explanation on how these costs are derived.

1.5 COST TABLES

Immediate Repair Cost

Item	Quantity	Unit	Unit Cost	Replacement Percent	Immediate Total
3.8 Accessibility (ADA) Compliance					
REPLACE OR RELOCATE DRINKING FOUNTAINS	6	EA	\$3,000.00	100%	\$18,000
Total Repair Cost					\$18,000.00

Capital Reserve Schedule

Item	EUL	EFF AGE	RUL	Quantity	Unit	Unit Cost	Cycle Replace	Replace Percent	Year 1 2021	Year 2 2022	Year 3 2023	Year 4 2024	Year 5 2025	Year 6 2026	Year 7 2027	Year 8 2028	Year 9 2029	Year 10 2030	Year 11 2031	Year 12 2032	Year 13 2033	Year 14 2034	Year 15 2035	Year 16 2036	Year 17 2037	Year 18 2038	Year 19 2039	Year 20 2040	Total Cost	
3.2.4 Paving, Curbing, and Parking																														
ASPHALT PAVEMENT REPAIRS	20	0	20	4	EA	\$5,000.00	\$20,000	100%																					\$20,000	\$20,000
3.2.5 Flatwork																														
REPLACE CONCRETE SIDEWALK SECTIONS AS NEEDED	25	24	1	4	EA	\$2,500.00	\$10,000	100%	\$2,500					\$2,500					\$2,500					\$2,500						\$10,000
3.2.7 Recreational Facilities																														
REPLACE PLAYGROUND EQUIPMENT	20	15	5	1	EA	\$45,000.00	\$45,000	100%					\$45,000																	\$45,000
RESURFACE ASPHALT PLAY AREA	20	19	1	1	EA	\$10,000.00	\$10,000	100%	\$10,000																					\$10,000
3.3.3 Building Exteriors																														
REPOINT BRICKWORK AS NEEDED	20	0	20	1	LS	\$75,000.00	\$75,000	100%																					\$75,000	\$75,000
REPLACE SEALANTS	12	0	12	1	LS	\$25,000.00	\$25,000	100%												\$25,000										\$25,000
REPAIR/REPLACE WOOD CORNICE	50	49	1	1	EA	\$200,000.00	\$200,000	100%	\$200,000																					\$200,000
3.3.6 Roofing Systems																														
REPAIR SLATE SHINGLE ROOFING SYSTEM	50	49	1	4	EA	\$5,000.00	\$20,000	100%	\$5,000					\$5,000					\$5,000					\$5,000						\$20,000
3.4.1.2 Domestic Hot Water Production																														
REPLACE WATER HEATERS	15	9	6	2	EA	\$1,200.00	\$2,400	100%						\$2,400																\$2,400
3.4.2.1 Equipment																														
REPLACE BOILERS	20	15	5	2	EA	\$25,000.00	\$50,000	100%					\$50,000																	\$50,000
REPLACE AIR HANDLER	15	14	1	1	EA	\$10,000.00	\$10,000	200%	\$10,000															\$10,000						\$20,000

City of Charlottesville - Facilities Development
 ECS Project No. 46:6713
 October 28, 2021

Item	EUL	EFF AGE	RUL	Quantity	Unit	Unit Cost	Cycle Replace	Replace Percent	Year 1 2021	Year 2 2022	Year 3 2023	Year 4 2024	Year 5 2025	Year 6 2026	Year 7 2027	Year 8 2028	Year 9 2029	Year 10 2030	Year 11 2031	Year 12 2032	Year 13 2033	Year 14 2034	Year 15 2035	Year 16 2036	Year 17 2037	Year 18 2038	Year 19 2039	Year 20 2040	Total Cost
REPLACE WATER SOURCE HEAT PUMPS	20	19	1	52	EA	\$2,500.00	\$130,000	100%	\$25,000								\$25,000					\$25,000	\$25,000		\$10,000	\$10,000	\$10,000		\$130,000
REPLACE COOLING TOWER	18	17	1	1	EA	\$30,000.00	\$30,000	100%	\$30,000																				\$30,000
REPLACE SPACE HEATERS	20	15	5	2	EA	\$1,000.00	\$2,000	100%				\$1,000										\$1,000							\$2,000
REPLACE SPLIT SYSTEM	15	9	6	1	EA	\$2,000.00	\$2,000	100%					\$2,000																\$2,000
REPLACE CONDENSOR AT ANNEX	15	14	1	1	LS	\$5,000.00	\$5,000	100%	\$5,000																				\$5,000
REPLACE SPACE HEATERS	20	19	1	2	EA	\$1,000.00	\$2,000	100%	\$2,000																				\$2,000
3.4.3.1 Service and Metering																													
REPLACE GENERATOR AND TRANSFER SWITCH	25	24	1	1	EA	\$30,000.00	\$30,000	100%	\$30,000																				\$30,000
3.6.2 Alarm Systems																													
REPLACE FIRE ALARM PANELS AS NEEDED	30	20	10	1	EA	\$30,000.00	\$30,000	100%										\$30,000											\$30,000
3.7.1 Interior Finishes																													
RENOVATE ANNEX INTERIORS AS NEEDED	30	29	1	1	LS	\$75,000.00	\$75,000	100%	\$75,000																				\$75,000
Total (Uninflated)									\$394,500.00	\$0.00	\$0.00	\$0.00	\$96,000.00	\$11,900.00	\$0.00	\$0.00	\$25,000.00	\$30,000.00	\$7,500.00	\$25,000.00	\$0.00	\$25,000.00	\$26,000.00	\$17,500.00	\$10,000.00	\$10,000.00	\$10,000.00	\$95,000.00	\$783,400.00
Inflation Factor (2.5%)									1.0	1.025	1.051	1.077	1.104	1.131	1.16	1.189	1.218	1.249	1.28	1.312	1.345	1.379	1.413	1.448	1.485	1.522	1.56	1.599	
Total (inflated)									\$394,500.00	\$0.00	\$0.00	\$0.00	\$105,966.04	\$13,463.76	\$0.00	\$0.00	\$30,460.07	\$37,465.89	\$9,600.63	\$32,802.17	\$0.00	\$34,462.78	\$36,737.32	\$25,345.22	\$14,845.06	\$15,216.18	\$15,596.59	\$151,871.77	\$918,333.46
Evaluation Period:									20																				
# of Square Feet:									61,720																				
Reserve per Square Feet per year (Uninflated)									\$0.63																				
Reserve per Square Feet per year (Inflated)									\$0.74																				

2.0 PURPOSE AND SCOPE

2.1 SCOPE OF SERVICES

This Facility Condition Assessment (FCA) was conducted in general accordance with items and terminology requested by the Owner herein and ASTM E 2018-15, "Standard Guide for Property Condition Assessments: Baseline Property Condition Assessment Process".

The primary purpose of a FCA is to note construction deficiencies and to identify components which appear to exhibit less than expected service life or which have been poorly maintained. The assessment is not intended to develop detailed remedial plans for identified problems. The services are qualitative in nature and do not include engineering calculations or design. Photographic documentation of our observations is attached.

The following building systems were observed in accordance with ASTM E 2018-15:

- Site Conditions
- Structural Frame and Building Envelope
- Plumbing, Mechanical and Electrical Systems
- Vertical Transportation Systems
- Life Safety and Fire Protection
- Interior Elements
- ADA Considerations
- Building Code Violations

Out of Scope Items

Environmental issues and concerns are considered to be outside of the ASTM scope of services for a Facility Condition Assessment. Although properties may have possible environmental contamination, including, but not limited to radon, mold, lead based paint, asbestos, lead piping, PCB's or volatile chemicals, these issues and concerns should be addressed by an Environmental Assessment, as defined by ASTM Guidelines. ECS recommends that properties be studied by a qualified environmental assessor who can appropriately access, identify, and quantify issues related to environmental safety concerns.

ECS is providing a Facility Condition Assessment consistent with commercial and customary practices and the ASTM E-2018, current at the time the services are provided. The parties expressly acknowledge and agree that ECS is not providing a Reserve Study, which is subject to the National Reserve Study Standards and requires much more detail than a typical Facility Condition Assessment.

2.2 Deviations from Guide (ASTM E2018-15)

ASTM E2018-15 requires that any deviations from the Guide be noted within the report. ECS reduced the cost threshold from \$3,000 to \$1,000 to allow for smaller items needing repair, replacement or refurbishment. Therefore items with costs less than \$1,000 are typically not included in this report unless related to life, safety or accessibility items.

ECS interviewed personnel associated with the Venable Elementary School facility and other government agencies based upon availability. These individuals are identified in Section 4.2. Information obtained from the interviews are included in the applicable sections of this report.

2.3 ASSESSMENT PROCEDURES

The FCA included site reconnaissance, limited interviews with property management, and inquiries or attempted inquiries with the local building and fire departments. Operational testing of building systems or components was not conducted. During the FCA, ECS conducted observations of the following facility features: site development systems; building structure systems; building exterior systems; building interior systems; roof systems; mechanical systems; electrical systems; plumbing systems; and life and fire safety systems.

This report is intended for review as a complete document. Therefore, interpretations and conclusions drawn from the review of any individual section are the sole responsibility of the User.

2.4 DEFINITIONS

Fair, adj - the property or component is functional but will likely require immediate maintenance or repairs during the duration of the term.

Good, adj - the property or component is functional and should continue to provide its intended service with continued routine maintenance through the duration of the term.

Poor, adj - the property or component is not functional. Immediate or near term repairs are required to bring the component back into service or replacement is expected during the duration of the term.

2.4.1 Partial List of ASTM Definitions

de minimis condition - a physical deficiency that is not material to the conclusions of the report.

deferred maintenance, n - physical deficiencies that could have been remedied with routine maintenance, normal operating maintenance, etc., excluding de minimis conditions that generally do not present a material physical deficiency to the subject property.

easily visible, adj - describes items, components, and systems that are conspicuous, patent, and which may be observed visually during the walk-through survey without: intrusion, relocation or removal of materials, exploratory probing, use of special protective clothing, or use of any equipment (hand tools, meters of any kind, telescope instruments, stools, ladders, lighting devices, etc.).

effective age, n - the estimated age of a building component that considers actual age as affected by maintenance history, location, weather conditions, and other factors. Effective age may be more or less than actual age.

expected useful life (EUL), n - the average amount of time in years that an item, component or system is estimated to function without material repair when installed new and assuming routine maintenance is practiced.

immediate cost, n - opinions of costs that require immediate action as a result of any of the following: (1) material existing or potentially unsafe conditions, (2) material building or fire code violations, (3) physical deficiencies that if left uncorrected would be expected to result in or contribute to critical element or system failure within on year or will result most probably in significant escalation of its remedial cost.

observation, n - the visual survey of items, systems, conditions, or components that are readily accessible and easily visible during a walk-through survey of the subject property.

observe, v - to conduct an observation pursuant to this guide within the context of easily visible and readily accessible.

obvious, adj - plain, evident, and readily accessible; a condition easily visible or fact not likely to be ignored or overlooked by a field observer when conducting a walk-through survey or that which is practically reviewable and would be understood easily by a person conducting the FCA.

opinions of costs, n - opinion of costs that may be encountered in correction of physical deficiencies.

physical deficiency, n - a conspicuous defect or deferred maintenance of a subject property's material systems, components, or equipment as observed during the completion of the FCA. - This definition specifically excludes deficiencies that may be remedied with routine maintenance, miscellaneous minor repairs, normal operating maintenance, etc., and excludes de minimis conditions that generally do not present material physical deficiencies of the subject property.

Point of Contact (POC), n - owner, owner's agent, or user-identified person or persons knowledgeable about the physical characteristics, maintenance, and repair of the subject property.

practically reviewable, adj - describes information that is provided by the source in a manner and form that, upon review, yields information relevant to the subject property without the need for significant analysis, measurements, or calculations. Records or information that feasibly cannot be retrieved by reference to the location of the subject property are not generally considered practically reviewable.

primary commercial real estate improvements, n - the site and building improvements that are of fundamental importance with respect to the commercial real estate. This definition specifically excludes ancillary structures, that may have been constructed to provide support uses such as maintenance sheds, security booths, utility garages, pool filter and equipment buildings, etc.

property, n - the site improvements, which are inclusive of both site work and buildings.

readily accessible, adj - describes areas of the subject property that are promptly made available for observation by the field observer at the time of the walk-through survey and do not require the removal or relocation of materials or personal property, such as furniture, floor, wall, or ceiling coverings; and that are safely accessible in the opinion of the field observer.

readily available, adj - describes information or records that are easily and promptly provided to the consultant upon making a request in compliance with an appropriate inquiry and without the need for the consultant to research archive files.

reasonably ascertainable, adj - describes information that is publicly available, as well as readily available, provided to the consultant's offices from either its source or an information research/retrieval service within reasonable time, practically reviewable, and available at a nominal cost for either retrieval, reproduction or forwarding.

remaining useful life (RUL), n - a subjective estimate based upon observations, or average estimates of similar items, components, or systems, or a combination thereof, of the number of remaining years that an item, component, or system is estimated to be able to function in accordance with its intended purpose before warranting replacement. Such period of time is affected by the initial quality of an item, component, or system, the quality of the initial installation, the quality and amount of preventive maintenance exercised, climatic conditions, extent of use, etc.

representative observations, n - observations of a reasonable number of samples of repetitive systems, components, areas, etc., which are conducted by the field observer during the walk-through survey. The concept of representative observations extends to all conditions, areas, equipment, components, systems, buildings, etc., to the extent that they are similar and representative of one another.

routine maintenance, n - a repair that does not require specialized equipment, profession services, or contractors, but rather can be corrected within budget and skill set of typical property maintenance staff.

short term cost, n - opinions of costs to remedy physical deficiencies, such as deferred maintenance, that may not warrant immediate attention, but require repairs or replacements that should be undertaken on a priority basis in addition to routine preventive maintenance.

technically exhaustive, adj - describes the use of measurements, instruments, testing, calculations, exploratory probing or discovery, or other means to discover, or a combination thereof, or troubleshoot physical deficiencies or develop architectural or engineering findings, conclusions, and recommendations, or combination thereof.

3.0 SYSTEM DESCRIPTION AND OBSERVATIONS

3.1 PROPERTY DESCRIPTION

The Property contains a Two-story School building.

3.1.1 Property Location

The Property is located at 406 14th Street NW in Charlottesville, Virginia.

Surrounding Properties	
North	Gordon Avenue
East	Residential properties
South	Residential properties
West	14 Street NW

A Site Location Map and Aerial View are included in Appendix I.

3.1.2 Construction History

We understand that the building was constructed approximately 96 years ago in 1925.

3.1.3 Current Property Improvements

The School building, located at 406 14th Street NW, in Charlottesville, Virginia, consists of a Two-story building and an Annex building. The building totals approximately 61,720 square feet. Parking is provided with At-grade parking with asphalt pavement.

3.2 SITE CONDITIONS

3.2.1 Topography

TOPOGRAPHY		
Item	Description	Condition
Slope of the property	The property generally slopes to the southeast	Good
Adjoining Properties	Generally down slope	Good

Comments

The property is generally level and slopes to the southeast. The adjoining properties are located down gradient from the property.

3.2.2 Storm Water Drainage

STORM WATER DRAINAGE		
Item	Description	Condition
Storm Water Collection System	Municipal	Good
Storm Water (Retention) Pond	Bioretention basin at southeast of parking lot	Good
Storm Water Filtration Structure		N/A
Pavement Drainage	Bioretention basin	Good
Landscape Drainage	Gravity run off	Good
Sump Pumps		N/A

Comments

The storm water collection system is a municipal system. The parking lot on the east side of the building drains into a bioretention basin.

3.2.3 Access and Egress

SITE ACCESS AND EGRESS		
Item	Description	Condition
Entrance Aprons	Concrete	Good
Fire Truck Access	West and north sides of the property	Good
Easements		N/A

Comments

Vehicular access to the site is located on the north and west side of the property. The entrance apron is constructed of concrete and was observed to be in generally good condition. Fire truck access is available on the north side of the building.

3.2.4 Paving, Curbing, and Parking

PARKING		
Item	Description	Condition
Striping	Painted	Fair
Quantity of Parking Spaces	51	Good
Quantity of Loading Spaces		N/A
Arrangement of Spaces	Diagonal and perpendicular in east lot, parallel at west drive lane	Good
Site Circulation	One way drive aisle	Good
Lighting		N/A
Accessible Spaces	Three	Poor
Accessible Aisles	Two	Good

SURFACE PAVEMENT		
Item	Description	Condition
Pavement Surface	At-grade parking with asphalt pavement	Fair
Drainage	Bioretention basin	Good
Repair History	Patching noted	Fair
Concrete Curbs and Gutters		Fair
Dumpster Pad	Concrete	Fair
Asphalt Curbs		N/A
Fire Lane Painting	Painted curb and asphalt	Good

Comments

Asphalt-paved drive lanes and parking areas are located on the north and east sides of the site which also provides access to the site. Additional parking is provided along the western drive lane. The asphalt pavement was observed to be in generally good to fair condition with minor cracks observed on the pavement. Striping was in fair condition. The expected useful life of asphalt pavement is 20 years. It is understood asphalt repairs were in progress soon after our site visit. We recommend asphalt repairs near the end of the report period as needed.

Photographs



Asphalt pavement - note cracking



Asphalt pavement - note cracking

Recommendations

Cost Recommendation	EUL	EFF AGE	RUL	Year	Cost
ASPHALT PAVEMENT REPAIRS	20	0	20	20	\$20,000
Total					\$20,000

3.2.5 Flatwork

SIDEWALKS		
Item	Description	Condition
Walkways	Concrete and brick pavers	Fair
Patios	Concrete and brick pavers	Good
Steps	Concrete	Good
Landings	Concrete	Good
Handrails	Metal tube	Good
Ramps	Concrete	Good
Curb Ramps	Concrete	Good
Truncated Domes	Inset plastic	Good

Comments

At the perimeter of the building, concrete sidewalks of undetermined thickness are provided. Regularly spaced control joints were observed. The concrete sidewalks were generally in fair condition, with some cracked sections observed. We recommend the cracked and settled sections be replaced as necessary.

The steps and ramps were observed to be in generally fair condition. Previously repaired concrete steps appeared to be in fair condition. The handrails adjacent to the steps and ramps were observed to be in generally good condition. We recommend repairing the concrete steps as needed during the report period.

A brick paver sidewalk is located on the southwest side of the site. The brick paver sidewalk was in good condition.

Photographs



Typical concrete sidewalk



Typical concrete sidewalk - note cracking



Typical concrete sidewalk



Curb ramp



Typical concrete sidewalk - note cracking



Brick paver sidewalk



Brick paver sidewalk



Concrete stairs at the west side of the building

Recommendations

Cost Recommendation	EUL	EFF AGE	RUL	Year	Cost
REPLACE CONCRETE SIDEWALK SECTIONS AS NEEDED	25	24	1	1	\$2,500
				6	\$2,500
				11	\$2,500
				16	\$2,500
Total					\$10,000

3.2.6 Landscaping and Appurtenances

LANDSCAPING		
Item	Description	Condition
Trees	Located throughout the site	Good
Planting Beds	Located throughout the site	Good
Lawn Areas	Located throughout the site	Good
Irrigation System		N/A
Monumental Sign	Located at north entrance	Good
Landscape Lighting		N/A
Retaining Walls	Brick	Good
Fences and Gates	Chain link	Good
Dumpster Area	Located at east end of the building	Good

LANDSCAPING		
Item	Description	Condition
Fountains		N/A

Comments

The landscaping consists generally of mature trees, various shrubs, and grassed areas around the site. The landscaping was observed to be in generally good condition.

Brick retaining walls are located in various locations around the site. The retaining walls were observed to be in good condition.

A metal chain link fence is located on the east side of the site and was generally in good condition.

A sign is located at the north entrance. It is a painted wooden sign. The painted wooden sign was generally in good condition. We recommend painting the wood sign as a maintenance item as needed.

Photographs



Typical landscaping



Typical landscape

3.2.7 Recreational Facilities

PLAYGROUND		
Item	Description	Condition
Playing Surface	Asphalt and mulched areas	Good/Fair
Fencing	Chain link	Good
Equipment	Plastic/coated steel	Good/Fair

PLAYGROUND		
Item	Description	Condition
Lighting		N/A

Comments

Various playground equipment is located on the south and east sides of the property. The playgrounds consisted of various plastic play equipment and were located on a mulched play surfaces. The playground equipment was in good condition and was reportedly replaced in 2006. Mulching of the playground when required is considering a maintenance item. The expected useful life of playground equipment is 15 to 20 years with proper maintenance. An allowance for replacement of the equipment is included later in the study period.

An asphalt play surface is located at the southeast side of the property. The surface was in generally fair condition with cracking and vegetative growth noted. We recommend the play surface is resurfaced during the report period.

Photographs



Playground at south end of site



Playground at northeast end of site



Asphalt pavement - note cracking



Playground at southeast end of site

Recommendations

Cost Recommendation	EUL	EFF AGE	RUL	Year	Cost
REPLACE PLAYGROUND EQUIPMENT	20	15	5	5	\$45,000
RESURFACE ASPHALT PLAY AREA	20	19	1	1	\$10,000
Total					\$55,000

3.2.8 Special Utility Systems

Item	Description	Condition
Water Well		N/A
Lift Station		N/A
Septic Field		N/A
Solar Power		N/A
Wind Power		N/A

Comments

The Property does not contain special utility systems.

3.3 STRUCTURAL FRAME AND BUILDING EXTERIOR

3.3.1 Foundation

FOUNDATION		
Item	Description	Condition
Load Bearing Support	Assumed shallow spread footings	Good
Basement		N/A
Crawl Space		N/A

Comments

The foundation of the building includes Assumed shallow spread footings. Large cracks were not observed in the exterior walls. The foundation system appeared to provide adequate structural support to the building. The foundation was generally in good condition.

3.3.2 Building Frame

BUILDING FRAME		
Item	Description	Condition
Floor Framing	Concrete	Good
Roof Framing	Wood trusses	Good
Columns	Steel	Good
Load Bearing Walls	Brick masonry	Good
Balconies		N/A
Decks		N/A

Comments

The structure of the building consists of Masonry bearing walls with wood framed roofing and steel framing for east additions. The structural frame of the building was generally in good condition.

3.3.3 Building Exteriors

EXTERIOR FINISHES		
Item	Description	Condition
Masonry	Brick	Fair
Glass Store Front		N/A
Glass Curtain Wall		N/A

EXTERIOR FINISHES		
Item	Description	Condition
Metal		N/A
Concrete	Precast	Fair
Wood Siding		N/A
Accent/Trim	Deteriorated cornice work	Poor
Covered Soffits	Vinyl soffit at north and south wings	Good
Awnings		N/A
Paint	Peeling paint on cornice work	Poor
Sealants	Various	Poor

Comments

The primary exterior of the buildings consist of brick veneer with wood trim and wood cornice and precast stone accents. The brick and mortar were observed to be deteriorated and the wood cornice was rotted through at multiple locations. At the time of our site visit, an exterior restoration project was in progress. The building exteriors were generally in fair to poor condition and under current repair. The expected useful life of mortared joints is approximately 20 years before re-pointing is required. Deterioration of mortar joints was observed. We recommend re-pointing of the deteriorated mortar joints as needed near the end of the report period. Exterior masonry repair activities were observed during the visit. We recommend the wood cornice be replaced.

The wood trim and exterior framing are painted. The paint was peeling. We recommend the wood trim be painted.

Exterior sealants are located around the window and door frames, horizontal joints, and vertical joints in the brick veneer. The expected useful life of exterior sealants is approximately 10 to 12 years before replacement is needed. The exterior sealants were generally in poor condition. The sealants were observed to be hard and separated from the substrate. We recommend that the exterior sealants be replaced during brick repointing.

Photographs



Building exterior west side of the building



Building exterior south side of the building



Building exterior - note rotten through cornice work



Building exterior - note rotten through cornice work



Building exterior - note cracking



Building exterior - note rotten through cornice work



Building exterior - note peeling paint



Building exterior - note deterioration

Recommendations

Cost Recommendation	EUL	EFF AGE	RUL	Year	Cost
REPOINT BRICKWORK AS NEEDED	20	0	20	20	\$75,000
REPLACE SEALANTS	12	0	12	12	\$25,000
REPAIR/REPLACE WOOD CORNICE	50	49	1	1	\$200,000
Total					\$300,000

3.3.4 Exterior Doors

DOORS		
Item	Description	Condition
Main Entrance Doors	Wood doors with glass	Good
Personnel Doors	Various	Good
Door Hardware	Varies	Good
Accessibility Controls		N/A
Overhead/Roll-up Doors		N/A

Comments

The main entrance is located at the west portion of the building and consists of Wood doors with glass. The main entrance doors were generally in good condition.

Metal and glass personnel doors are located throughout the building. The personnel doors were generally in good condition. It also appeared that many of the doors had been replaced over time. Exterior doors typically have an expected useful life of 20 to 30 years.

Photographs



Main entrance doors at west side of the building



Entrance doors at north side of the building



Typical personnel door

3.3.5 Exterior Windows

WINDOWS		
Item	Description	Condition
Window Frame	Aluminum framed	Good
Glass Pane	Double-pane	Good
Operation	Various	Good
Screen		N/A
Exterior Header	Varies with condition	Good
Exterior Sill	Varies with condition	Good
Gaskets or Glazing	Varies with condition	Good

Comments

The window system for the building primarily consists of aluminum frame single pane window units. The windows were observed to be in good condition. Aluminum single-pane windows have a typical expected useful life of 25 years.

It was noted that the paint on the steel lintels was cracking and peeling. The steel lintels should be repainted with the wood trim noted above.

Photographs



Typical exterior window



Typical exterior window - note peeling paint



Typical exterior windows



Typical exterior window - note peeling paint

3.3.6 Roofing Systems

ROOFING		
Item	Description	Condition
Slate Shingle	Located at west central portion of the building and Annex building	Fair
Metal	Located at north and south additions of the building and the Annex dormer	Good
Parapet Walls		N/A

ROOFING		
Item	Description	Condition
Cap Flashing/Coping		N/A
Insulation	Not observed	Good
Substrate/Deck	Varies	Good
Slope/Pitch		Good
Drainage	Gutters and downspouts	Good
Plumbing Vents	Varies with condition	Good
Exhaust Vents	Metal flashing	Good
Equipment Curbs		N/A
Pitch Pockets		N/A
Skylights		N/A
Flashing	Metal	Good
Expansion Joints		N/A
Roof Age	Varies	Fair

Comments

The original roofing system for the west central portion of the building consists of a slate shingle roofing system. Some of the slate shingles were misaligned and/or damaged. The slate shingle roofing system was generally in fair condition. We recommend a schedule of periodic repairs to the slate shingle roofing system as needed.

The building additions to the north and south consist of a standing seam metal roofing systems. The expected useful life of standing seam metal roofing systems is 50 years. The standing seam metal roofing systems were generally in good condition.

The Annex building had a slate shingle roofing system and a small shed dormer with a metal roof. Periodic repairs should include the Annex building.

Drainage for the roofing system is provided by gutters and downspouts. Roofing penetrations included plumbing vents and exhaust vents throughout the roofing system.



Photographs



Slate shingle roofing system



Slate shingle roofing system



Slate shingle roofing system - note damaged and misaligned shingles

Recommendations

Cost Recommendation	EUL	EFF AGE	RUL	Year	Cost
REPAIR SLATE SHINGLE ROOFING SYSTEM	50	49	1	1	\$5,000
				6	\$5,000
				11	\$5,000
				16	\$5,000
Total					\$20,000

3.4 PLUMBING, MECHANICAL, AND ELECTRICAL SYSTEMS

3.4.1 Plumbing Systems

3.4.1.1 Supply and Waste Piping

PLUMBING - WATER SUPPLY SYSTEM		
Item	Description	Condition
Piping Material	Copper	Good
Pipe Insulation	Fiberglass	Good
Water Shut-offs	Various	Good
Water Flow and Pressure		Good

PLUMBING - WASTE SUPPLY SYSTEM		
Item	Description	Condition
Piping Material	PVC and cast iron	Good
Vertical Vent Stacks	PVC and cast iron	Good
Clean-outs	PVC and cast iron	Good

Comments

Water Lines

The main water supply lines inside the building are Copper. The expected useful life of Copper piping is approximately 40 years. The water supply pipes were generally in good condition.

Waste Lines

The waste lines in the building are PVC and cast iron. The expected useful life of PVC and cast iron waste line is approximately 50 years. The waste lines were generally in good condition and it was observed that some pipes had been replaced over time.

3.4.1.2 Domestic Hot Water Production

HOT WATER PRODUCTION		
Item	Description	Condition
Heating Equipment	Gas domestic water heater	Fair
Water Storage	In water heaters	Good
Circulation Pumps		N/A

Comments

Domestic hot water to the building is provided by two Gas domestic water heaters. Both Gas domestic water heaters are located in the mechanical room on the north side of the building. The water heaters were manufactured by A. O. Smith in 2013.

The expected useful life of a Gas domestic water heater is approximately 15 years with proper maintenance. We recommend the Gas domestic water heaters be replaced during the study period.

Photographs



Gas domestic water heaters

Recommendations

Cost Recommendation	EUL	EFF AGE	RUL	Year	Cost
REPLACE WATER HEATERS	15	9	6	6	\$2,400
Total					\$2,400

3.4.2 HVAC Systems

3.4.2.1 Equipment

EQUIPMENT		
Item	Description	Condition
Boilers	Located in main utility room	Fair
Chillers		N/A

EQUIPMENT		
Item	Description	Condition
Cooling Towers	Located outside at east side of the building	Fair/Poor
Fan Coil Units	Located at annex	Fair
Condensing Units	Located at annex	Fair
Air Handlers	Located in main utility room	Fair/Poor
Package Units		N/A
Exhaust Fans	Various	Good
Split System	Located in main utility room	Fair
Water Source Heat Pumps (WSHP)	Located throughout the building	Fair
Space Heaters (wall or ceiling mounted)	Located in main utility room	Good

Comments

The school building is served by a Central plant HVAC system with supplemental heating/cooling equipment and includes a cooling tower, boilers, air handler, split system, and water source heat pumps. The annex building is served by a gas furnace air handler and condenser unit.

Boilers

The Patterson Kelly boilers have an expected useful life of 20 years with proper maintenance. The two boilers were located in the main utility room at the east side of the building. The boilers were installed in 2006 and were generally in fair condition. We recommend replacing the boilers during the report period.

Cooling Tower

The cooling tower is located at the east side of the building at the exterior enclosure near the south building addition. The Evapco cooling tower was installed in 2001 and was in fair to poor condition based on its age. Cooling towers have a typical expected useful life of approximately 18 years. The cooling tower should be replaced during the study period.

Air Handler

A large air handler was located in the main utility room on the east side of the building. The unit was manufactured by Trane in 1998 and was in fair to poor condition based on age. The expected useful life of air handlers is 15 years with proper maintenance. We recommend that the air handler be replaced during the report period.

Water Source Heat Pumps (WSHP)

There are approximately 52 WSHP units located throughout the building. The typical expected useful life of the water source heat pumps is 20 years and they were reportedly installed and/or replaced over time ranging from 1988 to 2016. We recommend a scheduled replacement of the units based on their age during the report period.

Split System

A Fujitsu split system was located in the main utility room. The system installation date was unknown and was in fair condition. Split systems have an expected useful life of 15 years and should be replaced during the study period.

Space Heaters

Two ceiling mounted space heaters were located in the main utility room. The space heaters were in fair condition. Replacement of the space heaters is included during the study period.

Annex Condenser Unit and Air Handler

The condenser unit was reportedly installed in 2000, manufactured by Trane, and has an expected useful life of 15 years with proper maintenance. The gas furnace, manufactured by Carrier, was reportedly installed in 2020. The condenser unit was located outside the annex. The units were generally in fair condition. We recommend replacing the condenser unit during the report period.

The City of Charlottesville self performs the mechanical service for the equipment.

Photographs



Boilers located in main utility room



Cooling tower located on east side of the building



Condenser unit at annex



Air Handler Unit located in main utility room



Typical older Water Source Heat Pump



Typical newer Water Source Heat Pump



Typical newer Water Source Heat Pump



Split system located in main utility room



Space heater located in main utility room

Recommendations

Cost Recommendation	EUL	EFF AGE	RUL	Year	Cost
REPLACE BOILERS	20	15	5	5	\$50,000
REPLACE AIR HANDLER	15	14	1	1 16	\$10,000 \$10,000

Cost Recommendation	EUL	EFF AGE	RUL	Year	Cost
REPLACE WATER SOURCE HEAT PUMPS	20	19	1	1	\$25,000
				9	\$25,000
				14	\$25,000
				15	\$25,000
				17	\$10,000
				18	\$10,000
			19	\$10,000	
REPLACE COOLING TOWER	18	17	1	1	\$30,000
REPLACE SPACE HEATERS	20	15	5	5	\$1,000
				15	\$1,000
REPLACE SPLIT SYSTEM	15	9	6	6	\$2,000
REPLACE CONDENSOR AT ANNEX	15	14	1	1	\$5,000
REPLACE SPACE HEATERS	20	19	1	1	\$2,000
Total					\$241,000

3.4.2.2 Distribution System

HVAC DISTRIBUTION		
Item	Description	Condition
Ducts	Metal	Good
Return Air	Metal	Good

Comments

The distribution system includes ducted supply and return. Exposed ductwork was observed in limited locations within the building and was in generally good condition.

3.4.2.3 Control Systems

HVAC CONTROL SYSTEMS		
Item	Description	Condition
Thermostats	Various	Good
Variable Frequency Drives	Located in main mechanical room	Good

HVAC CONTROL SYSTEMS		
Item	Description	Condition
Energy Management System	BAS	Good

Comments

The thermostats are located throughout the interior spaces. The thermostats were observed to be in generally good condition. It was reported that the existing NOVAR BAS (Building Automation System) is being phased out and an Allerton system that was installed in 2015 is replacing it. The BAS system was in good condition.

3.4.3 Electrical Systems

3.4.3.1 Service and Metering

SERVICE AND METERING		
Item	Description	Condition
Service Entrance	North side of building	Good
Master (House) Meter	Located in the east side of the building	Good
Emergency Power	Generator	Fair/Poor
Transfer Switch	Kohler	Fair/Poor

Comments

Electricity is provided to the building by Dominion Virginia Power. The main electrical entrance is located on the north side of the building and provides 2,000 amp, 3-phase, 4-wire service.

A Kohler emergency power generator is located at the north side of the building at the exterior enclosure near the mechanical room. The generator installation date was 1988. A typical expected useful life of 25 years. Based on the age of the emergency generator and typical replacement schedule, we recommend replacing the emergency generator during the report period.

The emergency back up power generator transfer switch was manufactured by Kohler and is located in the main mechanical room. The transfer switch installation date was unknown with an expected useful life of 25 years with proper maintenance. The transfer switch should be replaced in conjunction with the generator.

Photographs



Emergency power generator



Emergency power transfer switch

Recommendations

Cost Recommendation	EUL	EFF AGE	RUL	Year	Cost
REPLACE GENERATOR AND TRANSFER SWITCH	25	24	1	1	\$30,000
Total					\$30,000

3.4.3.2 Distribution

ELECTRICAL DISTRIBUTION SYSTEM		
Item	Description	Condition
Electrical Sub-panels	Various	Good
Branch Wiring	Copper	Good
GFCI Devices		Good
Building Transformers	Pad mounted	Good
Sub-Meters		N/A

Comments

Power is distributed by copper wire from circuit breaker panels located throughout the building. The expected useful life of sub-panels is 50 years with proper maintenance. The circuit breaker panels were reportedly recently replaced. The circuit breaker panels were observed to be in generally good condition.

3.5 VERTICAL TRANSPORTATION SYSTEMS

ELEVATORS		
Item	Description	Condition
Quantity	One passenger elevator	Good
Capacity	2,100 pounds	Good
Manufacturer and Type	Unknown	Good
Maintenance Contractor	KONE	Good
Date of Last Maintenance Inspection	2/22/2021	Good
Cab Finishes	Enamel	Good
Elevator Certificates	Located in Facilities Maint. Ofc.	Good
Door Sensors	Operable	Good
Speed	100 feet per minute	Good
Floor Leveling	Operable	Good
Control System	Operable	Good
Fire Recall System	Operable	Good
Lighting	Operable	Good
Equipment Room		Good

Comments

The elevator is located at the center of the original building. The manufacturer and installation date is unknown. The expected useful life of the elevator controls is 30 to 40 years with proper maintenance. Routine maintenance is considered adequate to keep the elevator system in good condition during the projection period of this report. The last annual inspection was performed in February 2021 by E&F Elevator Inspections and Consulting, Inc. and monthly maintenance is provided by KONE. The inspection reports are included in an appendix of this report.

Photographs



Elevator located at center of building



Elevator machine and controls

3.6 LIFE SAFETY AND FIRE PROTECTION

3.6.1 Sprinklers and Suppression Systems

SPRINKLER AND SUPPRESSION SYSTEMS		
Item	Description	Condition
Sprinkler System (wet)	Automatic	Good
Sprinkler Heads	Various	Good
Date of Last Inspection (sprinkler system)	4/6/2021	Good
Sprinkler Pump	Pad mounted	Good
Fire Extinguishers	Located throughout building	Good
Date of Last Inspection (Fire Extinguishers)	6/14/2021	Good
Fire Standpipes		Good
Fire Department Connections	Located on west side of building	Good
Hose Cabinets		N/A
Fire Hydrants	Located on streets	Good

Comments

The fire suppression system is a Wet sprinkler system and fire extinguishers. The fire suppression system was observed but not tested. The sprinklers are connected to the fire alarm. The sprinkler risers are located in the sprinkler room.

Sprinkler heads are located throughout the building. The sprinkler heads were generally in good condition.

Fire extinguishers were observed throughout the building including in mechanical rooms. The fire extinguishers were observed to have recent inspection tags issued by Fire Solutions in June of 2021. These devices are required to be inspected annually. Replacement of the fire extinguishers is considered routine maintenance.

Fire hydrants are located at the building exterior. The fire hydrants were observed to be in good condition.

Photographs



Fire sprinkler system



Fire sprinkler pump controller



Fire sprinkler pump controller



Typical fire extinguisher

3.6.2 Alarm Systems

ALARM SYSTEMS		
Item	Description	Condition
Public Address System	Located in main office	Good/Fair
Central Fire Alarm Control Panel	Located in main office	Good/Fair
Automatic Notification	Monitored	Good
Bells	Located throughout the building	Good
Strobes	Located throughout the building	Good
Exit Signs	Located throughout the building	Good
Exit Lights	Located throughout the building	Good
Pull Stations	Located throughout the building	Good
Smoke Detectors	Located throughout the building	Good
Carbon Monoxide Detectors		N/A

Comments

The fire alarm system was observed but not tested. A fire control panel is located at the main office. The fire control panel was observed to be in good condition. Emergency exit signs and lighting, pull stations, fire extinguishers, smoke detectors, and alarm bells and strobes are located throughout the building.

Photographs



Typical fire alarm bell and strobe



Typical fire alarm pull station



Typical smoke detector

Recommendations

Cost Recommendation	EUL	EFF AGE	RUL	Year	Cost
REPLACE FIRE ALARM PANELS AS NEEDED	30	20	10	10	\$30,000
Total					\$30,000

3.6.3 Security and Other Systems

SECURITY AND OTHER SYSTEMS		
Item	Description	Condition
Security Cameras		N/A
Alarm System		N/A
Access Control	Intercom	Good
Security Fencing		N/A
Lightning Protection		N/A
Roof Anchors		N/A

Comments

The building has hardware access controls. The security system was reported to be in good condition.

3.7 INTERIOR BUILDING COMPONENTS

3.7.1 Interior Finishes

MAIN OFFICE		
Item	Description	Condition
Floor Finishes	Carpet	Good
Wall Finishes	Painted gypsum board	Good
Ceiling Finishes	Suspended acoustical tile, painted gypsum board	Good
Lighting	Fluorescent fixtures	Good
Accessories	Built-in cabinetry	Good

RESTROOMS		
Item	Description	Condition
Floor Finishes	Ceramic tile	Good
Wall Finishes	Ceramic tile, painted gypsum board	Good
Ceiling Finishes	Suspended acoustical tile	Good
Fixtures	Toilets, urinals, wall hung lavatories	Good
Accessories	Grab bars, mirrors, soap dispensers, hand dryers	Good

RESTROOMS		
Item	Description	Condition
Ventilation	Exhaust fans	Good
Lighting	Fluorescent fixtures	Good
Doors	wood	Good
Door Hardware	Operable	Good

CORRIDORS		
Item	Description	Condition
Floor Finishes	Vinyl tile	Good
Wall Finishes	Painted gypsum board	Good
Ceiling Finishes	Suspended acoustical tile	Good
Lighting	Fluorescent fixtures	Good
Doors	Wood	Good
Door Hardware	Operable	Good

STAIRS		
Item	Description	Condition
Location	East and west ends of the building	Good
Enclosure	Finished	Good
Framing Support	Steel	Good
Treads	Vinyl	Good
Risers	Steel	Good
Nosing	Vinyl	Good
Handrails	Steel	Good
Lighting	Fluorescent	Good
Pressurized Stairwells		N/A
Doors	Wood	Good
Door Hardware	Operable	Good

KITCHEN		
Item	Description	Condition
Floor Finishes	Ceramic tile	Good
Wall Finishes	Ceramic tile, painted gypsum board	Good
Ceiling Finishes	Suspended acoustical tile	Good
Counters	Stainless	Good
Sink	Stainless	Good
Cabinets	Stainless	Good
Appliances	Stainless	Good
Stove/Range	Commercial	Good
Exhaust Vent/Hood	Commercial	Good
Refrigerator	Commercial	Good
Dish Washer	Commercial	Good
Microwave Oven	Countertop	Good

UTILITY ROOMS/ MECHANICAL ROOMS		
Item	Description	Condition
Floor Finishes	Unfinished concrete	Good
Wall Finishes	Painted gypsum board/ CMU	Good
Ceiling Finishes	Unfinished	Good
Janitor Sink Area	Soiled	Good
Lighting	Fluorescent fixtures	Good

AUDITORIUM		
Item	Description	Condition
Floor Finishes	Carpet	Good
Wall Finishes	Painted CMU, gypsum	Good
Ceiling Finishes	Painted gypsum board	Good
Lighting	Fluorescent fixtures	Good
Seating	Theater	Good
Stage	Wood	Good

CAFETERIA		
Item	Description	Condition
Floor Finishes	Vinyl tile	Good
Wall Finishes	Glazed block CMU	Good
Ceiling Finishes	Suspended acoustical tile	Good
Lighting	Fluorescent fixtures	Good
Accessories	Folding tables	Good

CLASSROOMS		
Item	Description	Condition
Floor Finishes	Vinyl tile and/or carpet	Good
Wall Finishes	Painted gypsum board/ painted CMU	Good
Ceiling Finishes	Suspended acoustical tile	Good
Lighting	Fluorescent fixtures	Good
Doors	Wood	Good
Door Hardware	Operable	Good

LIBRARY		
Item	Description	Condition
Floor Finishes	Carpet	Good
Wall Finishes	Painted gypsum board/ painted CMU	Good
Ceiling Finishes	Unfinished & acoustical ceiling tile	Good
Lighting	Fluorescent fixtures	Good
Doors	Wood	Good
Door Hardware	Operable	Poor

Comments

The interior building areas include a main office, restrooms, corridors, classrooms, a kitchen, an auditorium, a cafeteria, a library, and mechanical/utility spaces. We understand that the interiors are largely original to construction.

The finishes in the main office include carpet floors, and painted gypsum board walls, and both painted gypsum board and suspended acoustical ceiling tile ceilings. The finishes in the main office were observed to be in generally good condition.

Restrooms are located throughout the building as accessed from corridors and are also located in classrooms. The finishes in the restrooms include ceramic tile floors, ceramic tile and painted concrete masonry unit or gypsum walls, and suspended acoustical tile ceilings. The restrooms were observed to be in generally good condition.

The finishes in the corridors include vinyl tile floors, painted gypsum board walls, and suspended acoustical tile ceilings. The finishes in the corridors were observed to be in generally good condition.

The finishes in the kitchens include ceramic tile floors and walls and suspended acoustical tile ceilings. The finishes in the kitchens were observed to be in generally good condition.

The utility and mechanical rooms were generally unfinished, with concrete floors and painted gypsum board walls. Some utility rooms had painted gypsum board walls.

The finishes in the auditorium consisted of carpet flooring in the seating area and wood at the stage. The walls consisted of painted CMU and the ceiling was painted gypsum board. The finishes were generally in good condition.

The finishes in the cafeteria area consisted of vinyl tile flooring, ceramic tile and painted gypsum board walls, and suspended acoustical tile ceiling. The finishes were generally in good condition.

The classrooms consist of vinyl tile flooring and/or carpet, painted gypsum board and/or painted CMU walls, and suspended acoustical tile ceilings. The finishes were generally in good condition.

The finishes in the library consist of carpet flooring, painted gypsum board walls, and acoustical ceiling tile ceilings. The finishes in the library were generally in good condition.

Photographs



Interior finishes main office area



Interior finishes corridor area



Interior finishes classroom area



Interior finishes classroom area

Recommendations

Cost Recommendation	EUL	EFF AGE	RUL	Year	Cost
RENOVATE ANNEX INTERIORS AS NEEDED	30	29	1	1	\$75,000
Total					\$75,000

3.8 Accessibility (ADA) Compliance

Comments

Facilities, including site features and buildings, completed and occupied after January 26, 1992 are required to comply fully with the Americans with Disabilities Act (ADA). Facilities constructed after this date must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG). Existing facilities constructed prior to this date are held to the lesser standard of complying with the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. Title III, for the purposes of the ECS scope of work is to address public accommodations. ECS will note work that shall remove architectural barriers in existing facilities, including communication barriers, that are structural in nature, where such removal is readily achievable and able to be carried out without much difficulty or expense.

The Venable Elementary School property is considered by the City of Charlottesville - Facilities Development to be within "areas of public accommodations" or a "commercial facility" and is therefore is subject to compliance with Title III of the ADA.

The parking area serving the property has a total of approximately 51 parking spaces. Of the parking spaces, Three are accessible with Three being van accessible. Accessibility requires that three accessible parking spaces be provided in parking areas with a total of 51 to 75 spaces. One in

six of the accessible parking spaces are required to be van accessible. A minimum of a 60-inch wide access aisle is required to be provided for every two accessible parking spaces. Accessible aisles were observed to be provided. The number of parking spaces provided does meet accessibility requirements.

Photographs



Accessible lift



Accessible restroom



Accessible parking space



Accessible ramp at south end the site

Recommendations

Cost Recommendation	EUL	EFF AGE	RUL	Year	Cost
REPLACE OR RELOCATE DRINKING FOUNTAINS	20	20	0	Immediate	\$18,000

Cost Recommendation	EUL	EFF AGE	RUL	Year	Cost
Total					\$18,000

Uniform Abbreviated Screening Checklist for the 2010 Americans with Disabilities Act			
	Item	Yes/ No	Comments
A.	History		
1.	Has an ADA Survey been completed for this property?	Yes	
2.	Have any ADA improvements been made to the property since original construction?	Yes	installation of accessible lifts
3.	Has building ownership/management reported any ADA complaints or litigation?	No	not reported
B.	Parking		
1.	Does the required number of standard ADA-designated spaces appear to be provided?	Yes	Three out of the 51 are accessible.
2.	Does the required number of van-accessible designated spaces appear to be provided?	Yes	two out of the Three accessible spaces are van accessible
3.	Are accessible spaces part of the shortest accessible route to an accessible building entrance?	Yes	
4.	Is a sign with the International Symbol of Accessibility at the head of each space?	No	lower level accessible space needs sign
5.	Does each accessible space have an adjacent access aisle?	Yes	
6.	Do parking spaces and access aisles appear to be relatively level and without obstruction?	Yes	
C.	Exterior Accessible Route		
1.	Is an accessible route present from public transportation stops and municipal sidewalks in the property?	Yes	
2.	Are curb cut ramps present at transitions through curbs on an accessible route?	Yes	

Uniform Abbreviated Screening Checklist for the 2010 Americans with Disabilities Act			
	Item	Yes/ No	Comments
3.	Do curb cut ramps appear to have the proper slope for all components?	Yes	
4.	Do ramps on an accessible route appear to have a compliant slope?	Yes	
5.	Do ramps on an accessible route appear to have a compliant length and width?	Yes	
6.	Do ramps on an accessible route appear to have a compliant end and intermediate landings?	Yes	
7.	Do ramps on an accessible route appear to have compliant handrails?	Yes	
D.	Building Entrances		
1.	Do a sufficient number of accessible entrances appear to be provided?	Yes	
2.	If the main entrance is not accessible, is an alternate accessible entrance provided?	N/A	
3.	Is signage provided indicating the location of alternate accessible entrances?	N/A	
4.	Do doors at accessible entrances appear to have compliant clear floor area on each side?	Yes	
5.	Do doors at accessible entrances appear to have compliant hardware?	Yes	
6.	Do doors at accessible entrances appear to have complaint opening width?	Yes	
7.	Do pairs of accessible entrance doors in series appear to have the minimum clear space between them?	N/A	
8.	Do thresholds at accessible entrances appear to have compliant height?	Yes	
E.	Interior Accessible Routes and Amenities		
1.	Does an accessible route appear to connect with all public areas inside the building?	Yes	
2.	Do accessible routes appear free of obstructions and/or protruding objects?	No	drinking fountains protrude into corridor

Uniform Abbreviated Screening Checklist for the 2010 Americans with Disabilities Act			
	Item	Yes/ No	Comments
3.	Do ramps on accessible routes appear to have compliant slope?	N/A	
4.	Do ramps on accessible routes appear to have compliant length and width?	N/A	
7.	Are adjoining public areas and areas of egress identified with accessible signage?	Yes	
8.	Do public transaction areas have an accessible, lowered counter section?	Yes	
9.	Do public telephones appear mounted with an accessible height and location?	N/A	
10.	Are publicly-accessible swimming pools equipped with an entrance lift?	N/A	
F.	Interior Doors		
1.	Do doors at interior accessible routes appear to have compliant clear floor area on each side?	Yes	
2.	Do doors at interior accessible routes appear to have compliant hardware?	Yes	
3.	Do doors at interior accessible routes appear to have compliant opening force?	Yes	
4.	Do doors at interior accessible routes appear to have a compliant clear opening width?	Yes	
G.	Elevators		
1.	Are hallway call buttons configured with the "UP" button above the "DOWN" button?	Yes	
2.	Is accessible floor identification signage present on the hoistway sidewalls?	Yes	
H.	Toilet Rooms		
1.	Do publicly-accessible toilet rooms appear to have a minimum compliant floor area?	Yes	
2.	Does the lavatory appear to be mounted at a compliant height and with compliant knee area?	Yes	

Uniform Abbreviated Screening Checklist for the 2010 Americans with Disabilities Act			
	Item	Yes/ No	Comments
3.	Does the lavatory faucet have compliant handles?	Yes	
4.	Is the plumbing piping under lavatories configured to protect against contact?	Yes	
5.	Are grab bars provided at compliant locations around the toilet?	Yes	
6.	Do toilet stall doors appear to provide the minimum compliant clear width?	N/A	
7.	Do toilet stalls appear to provide the minimum compliant clear floor area?	N/A	
8.	Do urinals appear to be mounted at a compliant height and with compliant approach width?	N/A	
9.	Do accessories and mirrors appear to be mounted at a compliant height?	Yes	

4.0 DOCUMENT REVIEW

4.1 DOCUMENTATION REVIEW

ECS requested relevant documentation from Josh Bontrager, to gain insight into the subject property's physical improvements, extent and type of use, and/or assist in identifying material discrepancies between reported information and observed conditions. ECS' review of documents submitted does not include commenting on the accuracy of such documents or their preparation, methodology, or protocol.

4.2 INTERVIEW SUMMARY

ECS was escorted through the property by Stewart Harding and Derek Tyler who provided information about the property.

5.0 ADDITIONAL CONSIDERATIONS

5.1 MOISTURE AND MOLD

Comments

If present, evidence of mold and moisture issues are noted in the interior section of the report.

6.0 RECOMMENDATIONS AND OPINIONS OF COST

The opinion of cost are based upon approximate quantities, costs, and published information, and they include labor, material, design fees, and appropriate overhead, general conditions, and profit. A detailed analysis of quantities for cost estimating purposes is not included. The opinion of cost to repair, replace, or upgrade the improvements are considered typical for the marketplace. No contractors have provided pricing. The actual cost of repairs may vary from our opinions. ECS has not included contingency funds in our opinions. Amounts indicated represent today's dollars. ECS offers the following comments relative to Immediate and Capital Reserves criteria:

Immediate Issues

Physical deficiencies that require immediate action as a result of (i) existing or potentially unsafe conditions, (ii) significant negative conditions impacting tenancy, (iii) material building code violations, (iv) poor or deteriorated condition of critical element or system, or (v) a condition that is left "as is," with an extensive delay in addressing same, would result in or contribute to critical element or system failure within one year.

ECS has also included physical deficiencies inclusive of deferred maintenance that may not warrant immediate attention, but requiring repairs or replacements that should be undertaken on a priority basis, taking precedence over routine preventative maintenance work within a zero to one year time frame. Included are such physical deficiencies resulting from improper design, faulty installation, and/or substandard quality of original systems or materials. Components or systems that have realized or exceeded their Expected Useful Life (EUL) that may require replacement to be implemented within a zero to one year time frame are also included.

Capital Reserves

Capital Reserves are for recurring probable expenditures, which are not classified as operational or maintenance expenses, which should be annually budgeted for in advance. Capital reserves are reasonably predictable both in terms of frequency and cost. However, they may also include components or systems that have an indeterminable life but nonetheless have a potential liability for failure within an estimated time period. A component method has also been included within this report as well.

Capital Reserves excludes systems or components that are estimated to expire after the reserve term and that are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that were not deemed to have a material affect on the use were also excluded. Costs that are caused by acts of God, accidents or other occurrences that are typically covered by insurance, rather than reserved funds, are also excluded.

Replacement costs were solicited from ownership/property management, ECS' discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by ownership's or property management's maintenance staff were also considered.

ECS's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the evaluation period. Additional information concerning systems or components respective replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Capital Reserve Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined in the Immediate Needs Cost Estimates.

7.0 FACILITY CONDITION INDEX (FCI)


In accordance with our proposal add alternate, ECS determined the Facility Condition Index (FCI) value for the Venable Elementary School buildings. ECS determined the FCI value in accordance with industry standards and methodology sponsored by The National Association of College and University Business Officers (NACUBO). The FCI calculation methodology consists of dividing the total cost of Maintenance, Repair, and Replacement Deficiencies of the Facility by the Current Replacement Value of the Facility. FCI values and condition of the buildings based on the industry accepted interpretation of FCI values with ratings: good (under 0.05), fair (0.05 to 0.10), and poor (over 0.10).

Based on our Facility Condition Assessment, the total repair and replacement costs for the Venable Elementary School is \$783,400. The replacement construction cost value obtained from the RS MEANS square foot estimator application is \$8,112,480. Please see attached documentation from RS MEANS program output as an appendix to the report. The calculated FCI value is determined to be 0.10. In accordance with the industry standards and methodology sponsored by The National Association of College and University Business Officers (NACUBO), the condition of the Venable School is rated as fair.

The letter rating for the school buildings is based on the FCI values with the ratings system provided by you referenced from the City of Alexandria as follows : A (under 0.10), B (0.11 to 0.20), C (0.21 to 0.40), D (0.41 to 0.60), and F (0.61 to 1.00+).


The letter rating for the Venable Elementary School was determined to be B.

Appendix I: SITE MAP AND AERIAL PHOTOGRAPH



Untitled Map





Untitled Map



Appendix II: FIRE EXTINGUISHER INSPECTION

Inspection Certificate

For

Charlottesville-Venable
Elementary
406 14th St.
Charlottesville, VA 22903

This Inspection was performed in accordance with applicable Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

*Annual Inspection
Inspection Date
Jul 9, 2021*

Building: Charlottesville-Venable Elementary
Contact: RJ Narkie
Title: Facility Mgr

Company: Fire Solutions
Contact: Christopher Bowmaster
Title: Technician

Executive Summary

Generated by: BuildingReports.com

Building Information									
Building: Charlottesville-Venable Elementary					Contact: RJ Narkie				
Address: 406 14th St.					Phone: 540				
Address:					Fax:				
City/State/Zip: Charlottesville, VA 22903					Mobile:				
Country: United States of America					Email:				
Inspection Performed By									
Company: Fire Solutions					Inspector: Christopher Bowmaster				
Address: 205 Haley Road					Phone: 804-994-1711				
Address:					Fax:				
City/State/Zip: Ashland, Virginia 23005					Mobile: 804-994-1711				
Country: United States					Email: cbowmaster@firesolutionsinc.com				
Inspection Summary									
Category:	Total Items		Serviced		Passed		Failed/Other		
	Qty	%	Qty	%	Qty	%	Qty	%	
Fire	19	100.00%	19	100.00%	19	100.00%	0	0%	
Totals	19	100%	19	100.00%	19	100.00%	0	0%	
Verification									
			Company: Fire Solutions			Building: Charlottesville-Venable Elementary			
			Inspector: Christopher Bowmaster			Contact: RJ Narkie			
									
			Signed: Jul 9, 2021						
Fire Solutions Certifications									
Certification Type						Number			
WBENC Certified						2005121836			

Inspection & Testing

Generated by: BuildingReports.com

Building: Charlottesville-Venable Elementary				
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed /Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	ScanID : S/N	Service	Date Time
Passed				
Fire				
Fire Extinguisher, 5 Lbs, A.B.C.	Basement boiler room 418.06	39853283 F75958872	Inspected	06/14/21 8:39:58 AM
Fire Extinguisher, 5 Lbs, A.B.C.	1st Auditorium stage left 418.19	39853276 HE278103	Inspected	06/14/21 8:20:52 AM
Fire Extinguisher, 5 Lbs, A.B.C.	1st Auditorium stage right 418.18	39853275 F51138586	Inspected	06/14/21 8:20:19 AM
Fire Extinguisher, 5 Lbs, A.B.C.	1st beside auditorium 418.08	39853277 F75958867	Inspected	06/14/21 8:22:01 AM
Fire Extinguisher, 5 Lbs, A.B.C.	1st beside room 1 418.01	39853292 F75958870	Inspected	06/14/21 8:29:27 AM
Fire Extinguisher, 5 Lbs, A.B.C.	1st beside room 105. 418.03	39853279 F75958852	Inspected	06/14/21 8:26:02 AM
Fire Extinguisher, 5 Lbs, A.B.C.	1st beside room 5 418.02	39853291 F75958874	Inspected	06/14/21 8:28:53 AM
Fire Extinguisher, 5 Lbs, A.B.C.	1st by gym 418.10	39853176 VV123460	Inspected	07/09/21 10:23:34 AM
Fire Extinguisher, 5 Lbs, A.B.C.	1st by room 101 418.07	39853278 F75958858	Inspected	06/14/21 8:23:00 AM
Fire Extinguisher, 5 Lbs, A.B.C.	1st elevator room M1 418.20 access from kitchen	39853290 G17169437	Inspected	06/14/21 8:24:57 AM
Fire Extinguisher, 5 Lbs, A.B.C.	1st in room 105. 418.22	39853281 G17167765	Inspected	06/14/21 8:27:21 AM
Fire Extinguisher, 6 Ltr, Class K	1st kitchen 418.04	39853282 AB778913	Inspected	06/14/21 8:24:03 AM
Fire Extinguisher, 5 Lbs, A.B.C.	1st stage area rear exit 418.09	39853177 YJ295249	Inspected	06/14/21 8:19:36 AM
Fire Extinguisher, 5 Lbs, A.B.C.	2nd beside room 202 418.11	39853284 F75958862	Inspected	06/14/21 8:35:09 AM
Fire Extinguisher, 5 Lbs, A.B.C.	2nd beside room 207 418.14	39853285 F75958877	Inspected	06/14/21 8:31:19 AM
Fire Extinguisher, 5 Lbs, A.B.C.	2nd employee lounge 208 418.21	39853289 G17171187	Inspected	06/14/21 8:32:40 AM
Fire Extinguisher, 5 Lbs, A.B.C.	2nd main office 418.12	61768880 G17171197	Inspected	06/14/21 8:34:16 AM

Device Type	Location	ScanID : S/N	Service	Date Time
<i>Passed</i>				
Fire				
Fire Extinguisher, 5 Lbs, A.B.C.	3rd beside room 302 418.16	39853287 F75958863	Inspected	06/14/21 8:36:14 AM
Fire Extinguisher, 5 Lbs, A.B.C.	3rd beside room 309 418.15	39853286 5 HI SA40 ABC	Inspected	06/14/21 8:36:41 AM

Service Summary

Generated by: BuildingReports.com

Building: Charlottesville-Venable Elementary		
<i>The Service Summary section provides an overview of the services performed in this report.</i>		
Device Type	Service	Quantity
<i>Passed</i>		
Fire Extinguisher, 5 Lbs, A.B.C.	Inspected	18
Fire Extinguisher, 6 Ltr, Class K	Inspected	1
Total		19
Grand Total		19

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Charlottesville-Venable Elementary				
<p><i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i></p>				
Device or Type	Category	% of Inventory	Quantity	
Fire Extinguisher	Fire	100.00%	19	
Type	Qty	Model #	Description	Manufacture Date
<i>New (under 90 days)</i>				
Buckeye				
Fire Extinguisher	5	5 HI SA40 ABC	A.B.C.	10/06/2021
<i>In Service - 1 Year to 2 Years</i>				
Buckeye				
Fire Extinguisher	9	5 HI SA40 ABC	A.B.C.	08/08/2019
<i>In Service - 2 Years to 3 Years</i>				
Amerex				
Fire Extinguisher	1	AB500-18	A.B.C.	08/08/2018
<i>In Service - 10 Years to 15 Years</i>				
Ansul				
Fire Extinguisher	1	XK01-2	Class K	10/06/2008
Amerex				
Fire Extinguisher	1	AB402-06	A.B.C.	08/08/2006
<i>In Service - 15 Years to 25 Years</i>				
Amerex				
Fire Extinguisher	1	AB500-03	A.B.C.	08/08/2003
<i>In Service - 25 Years or Older</i>				
Badger				
Fire Extinguisher	1	5MB-5H	A.B.C.	08/08/1987

Inspection Certificate

For

Charlottesville-Venable Annex
416 13th St.
Charlottesville, VA 22903

This Inspection was performed in accordance with applicable Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Jun 14, 2021

Building: Charlottesville-Venable Annex
Contact: Jason Davis
Title: Security Maint.

Company: Fire Solutions
Contact: Tommy VO
Title: Technician

Executive Summary

Generated by: BuildingReports.com

Building Information								
Building: Charlottesville-Venable Annex					Contact: Jason Davis			
Address: 416 13th St.					Phone: 434-964-6771			
Address:					Fax:			
City/State/Zip: Charlottesville, VA 22903					Mobile:			
Country: United States of America					Email: davisja@charlottesville.org			
Inspection Performed By								
Company: Fire Solutions					Inspector: Tommy VO			
Address: 205 Haley Road					Phone: 804-385-3301			
Address:					Fax:			
City/State/Zip: Ashland, Virginia 23005					Mobile: 804-385-3301			
Country: United States					Email: tommyv@firesolutionsinc.com			
Inspection Summary								
Category:	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Fire	2	100.00%	2	100.00%	2	100.00%	0	0%
Totals	2	100%	2	100.00%	2	100.00%	0	0%
Verification								
	Company: Fire Solutions				Building: Charlottesville-Venable Annex			
	Inspector: Tommy VO				Contact: Jason Davis			
Fire Solutions Certifications								
Certification Type						Number		
WBENC Certified						2005121836		

Inspection & Testing

Generated by: BuildingReports.com

Building: Charlottesville-Venable Annex

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed /Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	ScanID : S/N	Service	Date Time
<i>Passed</i>				
Fire				
Fire Extinguisher, 5 Lbs, A.B.C.	1st Office by copier 422.02	39853294 G17167770	Inspected	06/14/21 8:47:22 AM
Fire Extinguisher, 5 Lbs, A.B.C.	1st iSTEM lab 422.01	49753253 YA679619	Inspected	06/14/21 8:50:29 AM

Service Summary

Generated by: *BuildingReports.com*

Building: Charlottesville-Venable Annex		
<i>The Service Summary section provides an overview of the services performed in this report.</i>		
Device Type	Service	Quantity
<i>Passed</i>		
Fire Extinguisher, 5 Lbs, A.B.C.	Inspected	2
Total		2
Grand Total		2

Inventory & Warranty Report

Generated by: *BuildingReports.com*

Building: Charlottesville-Venable Annex				
<p><i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i></p>				
Device or Type	Category	% of Inventory	Quantity	
Fire Extinguisher	Fire	100.00%	2	
Type	Qty	Model #	Description	Manufacture Date
<i>New (under 90 days)</i>				
Buckeye				
Fire Extinguisher	1	5 HI SA40 ABC	A.B.C.	10/06/2021
<i>In Service - 15 Years to 25 Years</i>				
Amerex				
Fire Extinguisher	1	AB500-06	A.B.C.	04/04/2006

Appendix III: FIRE SPRINKLER INSPECTION

INSPECTION AND TESTING FORM OF WATER BASED FIRE PROTECTION SYSTEMS

1. PROPERTY INFORMATION

Name of property: Venable Elementary (4433-22903-00026)
 Address:
 Description of property:
 Name of property representative: City of Charlottesville (30548899), Jason Davis (434-964-6771) davisja@charlottesville.org
 Address: 315 4th St NW, Charlottesville, VA 22903
 Phone: 434-962-3643 Fax: 434-970-3026 E-mail: staplesk@charlottesville.org

2. TESTING INFORMATION

Testing Organization: SIEMENS Organization License No.:
 Address: 5106 Glen Alden Drive, Richmond, VA 23231
 Phone: 804-222-6680 Fax: None E-mail: None
 Start Date/Time: 05 Apr 2021 Completion Date/Time: 05 Apr 2021
 Contract Info: City of Cville Sprinkler (2600105673) Notification Number: 5102050597
 Inspection Type: Quarterly

NOTES: 1) All questions are to be answered Yes, No, or Not Applicable (NA). Explain all No answers in Parts 6, 7, or 8 of this form.
 2) Inspection, Testing, and Maintenance are to be performed with water supplies (including fire pumps) in service, unless the impairment procedures of NFPA 25 are followed.

3. GENERAL INFORMATION (TO BE COMPLETED BY OWNER)

Is the building fully sprinklered? _____
 Has the occupancy classification and hazard of contents remained the same since last inspection? _____
 Are all fire protection systems in service? _____
 Has the system remained in service without modification since last inspection? _____
 Have any fire systems, devices or alarms activated since the last inspection? _____
 If a fire has occurred since the last inspection, have all damaged sprinkler system components been replaced? _____

4. INSPECTOR'S SECTION

4.1 Inspections

Control valves in the correct (open or closed) position and free from external leaks? _____ Yes
 Control valves locked, sealed or supervised? _____ Yes
 Hydraulic nameplate (calculated systems) securely attached and legible? _____ Yes
 Alarm and/or dry pipe valves free from physical damage, trim valves in appropriate position and no leakage? _____ Yes
 Water flow alarm devices free from physical damage? _____ Yes
 Fire department connections visible, signage, accessible, free from damage, couplings free, and caps in place? _____ Yes
 Gauges in good condition showing normal pressure? _____ Yes
 Adequate heat in areas with wet piping? _____ Yes
 Post indicator valves are provided with a correct wrench and in the normal position? _____ (NA)
 Backflow preventers relief port on RPZ device not discharging? _____ (NA)
 For freezer systems, is the gauge near the compressor reading the same as the gauge near the dry-valve? _____ (NA)
 Pressure Reducing valves are in the open position, not leaking, maintain downstream pressure accordance with the design criteria, good condition, and handwheels not broken? _____ (NA)
 Valve encloser for pre-action, deluge and dry systems are above 40f? _____ (NA)

4.2 Testing

Post indicating valves opened until spring or torsion is felt in the rod, then backed off one-quarter turn? _____ (NA)
 Valve supervisory switches indicate movement? _____ (NA)
 Mechanical water flow alarm device passed tests by opening the inspector's test or bypass connection with alarms actuating and flow observed? _____ Yes

Electrical Waterflow (Vane type, Paddle-type, and Pressure Switch-type) alarm devices passed tests by opening the inspector's test connection or bypass connection with alarm actuating, and flow is observed?	(NA)
Priming level of dry pipe valves correct?	(NA)
Quick opening devices of dry pipe systems passed?	(NA)
Air compressor or nitrogen system in good condition per manufacture maintenance procedure?	Yes
Low air pressure signal of dry pipe system passed?	(NA)
Main Drain Test water pressure is within 10% reduction in full flow pressure compared to previous test?	(NA)

5. MAIN DRAIN / TRIP TESTS RESULTS

5.1 Report Totals

Total Qty	Functionally Tested Qty	Functionally Tested %	Visually Tested Qty	Visually Tested %	Failed Qty	Failed %
3	1	33.3%	2	66.7%	0	0%

5.2 Report Totals by Type

Total Qty	Functionally Tested Qty	Functionally Tested %	Visually Tested Qty	Visually Tested %	Failed Qty	Failed %	Device or System Type
1	0	0%	1	100%	0	0%	Dry Sprinkler Systems
1	0	0%	1	100%	0	0%	Wet Sprinkler Systems
1	1	100%	0	0%	0	0%	Sprinkler Waterflow Alarm Devices

5.3 Report Details by Type

Dry Sprinkler Systems																	
Row	Date	Address	Location	Model	Water Source	Source PSI	Test Pipe Size	Static PSI	Trip Test	Initial Air PSI	Tripped Air PSI	Trip Time (sec)	Restored Static PSI	Restore Time (sec)	5 Year Performed	Visual/Functional	Pass/Fail
1	04/05/21	01:Dry	Mechanical Room	3 inch CSC	Fire Pump	130	1.25	120	(NA)	38	NA	NA	120	1	No	Visual	Pass

Wet Sprinkler Systems																	
Row	Date	Address	Location	Model	Water Source	Source PSI	Test Pipe Size	Static PSI	Restore Time (sec)	5 Year Performed	Visual/Functional	Pass/Fail					
1	04/06/21	01:Wet	Mechanical Room	6 inch GEM F2001	Fire Pump	130	2	120	1	Yes	Visual	Pass					

Sprinkler Waterflow Alarm Devices																	
Row	Date	Address	Location	Model	Type	Visual/Functional	Pass/Fail										
1	04/05/21	01:Wet:WVG	Riser Room	Grinell	Mechanical	Functional	Pass										

6. COMMENTS

Address	Location	NFPA Classification	Comment:
01: Dry	Mechanical Room	Dry Sprinkler	5 Year service performed August 2020

7. DEFICIENCIES (ONLY RELATED TO NFPA 25)

A condition that will or has the potential to adversely impact the performance of a system or portion thereof but does not rise to the level of an impairment.

Address	Location	NFPA Classification	Deficiencies:
01: Dry	Mechanical Room	Dry Sprinkler	None
01: Wet	Mechanical Room	Wet Sprinkler	None to report.

8. IMPAIRMENTS

A condition where a fire protection system or unit or portion thereof is out of order, and the condition can result in the fire protection system or unit not functioning in a fire event.

Address	Location	NFPA Classification	Impairments:
01: Dry	Mechanical Room	Dry Sprinkler	None
01: Wet	Mechanical Room	Wet Sprinkler	None to report.

9. CERTIFICATION

This Testing Was Performed in Accordance with Applicable NFPA Standards.

I state that the information on this form is correct at the time and place of my inspection and that all equipment tested at this time was left in operational condition upon completion of this inspection except as noted in Parts 6, 7, and 8 above.

Name of Inspector: _____

Inspector License #: _____

Signature: CRAIG BROWN

Date: 4.5.21

10. ACCEPTANCE BY OWNER OR OWNER'S REPRESENTATIVE

Name of Owner or Representative: _____

Signature: _____

Date: _____


The owner and/or designated representative acknowledges the responsibility of the operating condition of the component parts at the time of this inspection. Pursuant to the National Fire Protection Association Form 25, Chapter 4, the owner is responsible for proper maintenance and care of the sprinkler system. It is agreed that the inspection service provided by the contractor as prescribed herein is limited to performing a visual inspection and/or routine testing, and any investigation or unscheduled testing, modification, maintenance, repair, etc., of the component parts is not included as part of the inspection work performed. It is understood that this inspection pertains to the condition of the sprinkler system on the day of inspection only. This inspection meets or exceeds NFPA 25 requirements and or local AHJ requirements. AHJ requirements supersede all other code requirements. The inspector shall not be liable for future defaults or defects in the sprinkler system which are beyond the inspector's control, including, but not limited to, failure from malicious tampering, accidents, lack of proper inspection, material failure or inadequate heating. The inspector can give no assurance, nor will be held liable, with regard to work that may have been previously performed or work performed at a future date by other companies. It is further understood that all information contained herein is provided to the best of the knowledge of the party providing such information.

Appendix IV: RS MEANS ESTIMATE FOR FACILITY CONDITION INDEX (FCI)

Square Foot Cost Estimate Report

Date: **10/26/2021**

Estimate Name	Venable School
	City of Charlottesville 406 14th Street NW Charlottesville Virginia 22903
Building Type	School, Elementary with Brick Veneer / Reinforced Concrete
Location	CHARLOTTESVILLE, VA
	2.00
Stories Height	12.00
Floor Area (S.F.)	61,720.00
LaborType	OPN
Basement Included	No
Data Release	Year 2021
Cost Per Square Foot	\$131.44
Total Building Cost	\$8,112,479.88



Costs are derived from a building model with basic components. Scope differences and market conditions can cause costs to vary significantly.

**** Stories entered is outside the range recommended by RSMMeans.**

Assembly Customization Type :

- ⊕ Added
- ◐ Partially Swapped
- Fully Swapped

		Quantity	% of Total	Cost Per SF	Cost
A Substructure			5.6%	\$5.46	\$337,264.85
A1010	Standard Foundations			\$2.89	\$178,585.66
	Foundation wall, CIP, 4' wall height, direct chute, .148 CY/LF, 7.2 PLF, 12" thick	1,334.00		\$1.46	\$90,233.09
	Strip footing, concrete, reinforced, load 11.1 KLF, soil bearing capacity 6 KSF, 12" deep x 24" wide	1,334.00		\$0.78	\$48,294.80
	Spread footings, 3000 PSI concrete, load 100K, soil bearing capacity 6 KSF, 4' - 6" square x 15" deep	109.72		\$0.65	\$40,057.76
A1030	Slab on Grade			\$2.46	\$152,087.34
	Slab on grade, 4" thick, non industrial, reinforced	30,860.00		\$2.46	\$152,087.34

		Quantity	% of Total	Cost Per SF	Cost
A2010	Basement Excavation			\$0.11	\$6,591.85
	Excavate and fill, 30,000 SF, 4' deep, sand, gravel, or common earth, on site storage	54,005.00		\$0.11	\$6,591.85
B Shell			30.3%	\$29.74	\$1,835,527.33
B1010	Floor Construction			\$0.70	\$43,178.06
	Cast-in-place concrete column, 12", square, tied, minimum reinforcing, 150K load, 10'-14' story height, 135 lbs/LF, 4000PSI	800.40		\$0.70	\$43,178.06
B1020	Roof Construction			\$7.33	\$452,532.58
	Roof, concrete, beam and slab, 25'x25' bay, 40 PSF superimposed load, 20" deep beam, 9" slab, 152 PSF total load	30,860.00		\$7.33	\$452,532.58
B2010	Exterior Walls			\$10.82	\$667,795.49
	Brick wall, composite double wythe, standard face/CMU back-up, 8" thick, perlite core fill, 3" XPS	22,411.20		\$10.82	\$667,795.49
B2020	Exterior Windows			\$5.79	\$357,288.13
	Windows, aluminum, awning, insulated glass, 4'-5" x 5'-3"	278.40		\$3.16	\$194,801.49
	Aluminum flush tube frame, for 1/4"glass, 1-3/4"x4", 5'x20' opening, three intermediate horizontals	3,201.60		\$1.15	\$71,141.31
	Glazing panel, insulating, 1" thick units, 2 lites, 1/4" float glass, clear	3,201.60		\$1.48	\$91,345.33
B2030	Exterior Doors			\$0.84	\$51,874.73
	Door, aluminum & glass, with transom, narrow stile, double door, hardware, 6'-0" x 10'-0" opening	5.49		\$0.59	\$36,541.53
	Door, steel 18 gauge, hollow metal, 1 door with frame, no label, 3'-0" x 7'-0" opening	5.49		\$0.25	\$15,333.20
B3010	Roof Coverings			\$4.01	\$247,648.73
	Roofing, single ply membrane, EPDM, 60 mils, loosely laid, stone ballast	30,860.00		\$0.86	\$53,372.37
	Insulation, rigid, roof deck, extruded polystyrene, 40 PSI compressive strength, 4" thick, R20	30,860.00		\$1.98	\$122,275.96
	Base flashing, rubber, neoprene, 1/16" thick, 24 ga galv reglet, 24 ga galv counter flashing	1,334.00		\$0.52	\$31,895.54
	Roof edges, aluminum, duranodic, .050" thick, 8" face	1,334.00		\$0.56	\$34,590.89
	Flashing, aluminum, no backing sides, .019"	1,334.00		\$0.09	\$5,513.97
B3020	Roof Openings			\$0.25	\$15,209.61
	Roof hatch, with curb, 1" fiberglass insulation, 2'-6" x 3'-0", galvanized steel, 165 lbs	5.49		\$0.11	\$6,897.28
	Smoke hatch, unlabeled, galvanized, 2'-6" x 3', not incl hand winch operator	5.49		\$0.13	\$8,312.33
C Interiors			20.7%	\$20.33	\$1,255,063.55

		Quantity	% of Total	Cost Per SF	Cost
C1010	Partitions			\$3.45	\$213,012.69
	Concrete block (CMU) partition, light weight, hollow, 6" thick, no finish	30,860.00		\$3.45	\$213,012.69
C1020	Interior Doors			\$1.55	\$95,563.28
	Door, single leaf, kd steel frame, hollow metal, commercial quality, flush, 3'-0" x 7'-0" x 1-3/8"	88.17		\$1.55	\$95,563.28
C1030	Fittings			\$1.05	\$64,911.32
	Toilet partitions, cubicles, ceiling hung, painted metal	61.72		\$0.71	\$43,975.93
	Chalkboards, liquid chalk type, aluminum frame & chalktrough	1,234.40		\$0.34	\$20,935.39
C3010	Wall Finishes			\$3.30	\$203,550.58
	2 coats paint on masonry with block filler	61,720.00		\$2.00	\$123,210.40
	2 coats paint on masonry with block filler	22,411.20		\$0.72	\$44,739.03
	Ceramic tile, thin set, 4-1/4" x 4-1/4"	6,172.00		\$0.58	\$35,601.15
C3020	Floor Finishes			\$5.76	\$355,210.94
	Carpet, tufted, nylon, roll goods, 12' wide, 36 oz	6,172.00		\$0.49	\$30,108.50
	Carpet, padding, add to above, 2.7 density	6,172.00		\$0.09	\$5,539.49
	Terrazzo, maximum	6,172.00		\$1.88	\$116,118.77
	Vinyl, composition tile, maximum	37,032.00		\$1.46	\$90,357.71
	Oak strip, sanded and finished, minimum	12,344.00		\$1.44	\$89,173.30
	Underlayment, plywood, 3/8" thick	12,344.00		\$0.39	\$23,913.17
C3030	Ceiling Finishes			\$5.23	\$322,814.73
	Acoustic ceilings, 3/4" mineral fiber, 12" x 12" tile, concealed 2" bar & channel grid, suspended support	61,720.00		\$5.23	\$322,814.73
D Services			43.2%	\$42.45	\$2,619,969.66
D2010	Plumbing Fixtures			\$6.93	\$427,672.08
	Water closet, vitreous china, bowl only with flush valve, wall hung	61.72		\$3.31	\$204,308.63
	Urinal, vitreous china, wall hung	20.57		\$0.40	\$24,610.13
	Lavatory w/trim, wall hung, PE on CI, 20" x 18"	61.72		\$1.66	\$102,243.81
	Kitchen sink w/trim, countertop, stainless steel, 43" x 22" double bowl	8.23		\$0.31	\$19,082.18
	Service sink w/trim, PE on CI, wall hung w/rim guard, 24" x 20"	2.74		\$0.19	\$11,924.10
	Water cooler, electric, wall hung, wheelchair type, 7.5 GPH	31.55		\$1.06	\$65,503.23
D2020	Domestic Water Distribution			\$0.73	\$44,819.34
	Gas fired water heater, commercial, 100< F rise, 300 MBH input, 278 GPH	2.33		\$0.73	\$44,819.34
D2040	Rain Water Drainage			\$0.89	\$54,950.24

		Quantity	% of Total	Cost Per SF	Cost
	Roof drain, CI, soil, single hub, 5" diam, 10' high	20.57		\$0.81	\$49,920.68
	Roof drain, CI, soil, single hub, 5" diam, for each additional foot add	102.87		\$0.08	\$5,029.56
D3010	Energy Supply			\$9.19	\$567,140.14
	Commercial building heating system, fin tube radiation, forced hot water, 10,000 SF, 100,000 CF, total 2 floors	61,720.00		\$9.19	\$567,140.14
D3050	Terminal & Package Units			\$9.72	\$600,208.48
	Splt sys, air cooled condensing unit, schools and colleges, 20,000 SF, 76.66 ton	61,720.00		\$9.72	\$600,208.48
D4010	Sprinklers			\$2.47	\$152,293.48
	Wet pipe sprinkler systems, steel, light hazard, 1 floor, 50,000 SF	61,720.00		\$2.47	\$152,293.48
D4020	Standpipes			\$0.45	\$27,836.95
	Wet standpipe risers, class III, steel, black, sch 40, 4" diam pipe, 1 floor	1.37		\$0.21	\$13,216.17
	Wet standpipe risers, class III, steel, black, sch 40, 4" diam pipe, additional floors	6.86		\$0.24	\$14,620.78
D5010	Electrical Service/Distribution			\$0.70	\$42,899.14
	Overhead service installation, includes breakers, metering, 20' conduit & wire, 3 phase, 4 wire, 120/208 V, 800 A	1.25		\$0.21	\$12,698.44
	Feeder installation 600 V, including RGS conduit and XHHW wire, 800 A	60.00		\$0.15	\$9,386.70
	Switchgear installation, incl switchboard, panels & circuit breaker, 120/208 V, 3 phase, 800 A	1.20		\$0.34	\$20,814.00
D5020	Lighting and Branch Wiring			\$8.30	\$512,315.81
	Receptacles incl plate, box, conduit, wire, 8 per 1000 SF, .9 W per SF, with transformer	61,720.00		\$2.43	\$150,146.24
	Wall switches, 2.0 per 1000 SF	61,720.00		\$0.33	\$20,244.16
	Miscellaneous power, 1.2 watts	61,720.00		\$0.25	\$15,355.94
	Central air conditioning power, 4 watts	61,720.00		\$0.51	\$31,705.56
	Fluorescent fixtures recess mounted in ceiling, 1.6 watt per SF, 40 FC, 10 fixtures @32watt per 1000 SF	70,978.00		\$4.78	\$294,863.91
D5030	Communications and Security			\$3.01	\$185,570.72
	Communication and alarm systems, includes outlets, boxes, conduit and wire, sound systems, 12 outlets	0.85		\$0.24	\$14,842.47
	Communication and alarm systems, fire detection, addressable, 100 detectors, includes outlets, boxes, conduit and wire	1.71		\$1.68	\$103,770.18
	Fire alarm command center, addressable with voice, excl. wire & conduit	1.37		\$0.26	\$16,117.15

		Quantity	% of Total	Cost Per SF	Cost
	Communication and alarm systems, includes outlets, boxes, conduit and wire, master clock systems, 10 rooms	0.92		\$0.28	\$17,016.28
	Communication and alarm systems, includes outlets, boxes, conduit and wire, master TV antenna systems, 12 outlets	1.43		\$0.28	\$17,013.95
	Internet wiring, 2 data/voice outlets per 1000 S.F.	37.03		\$0.27	\$16,810.68
D5090	Other Electrical Systems			\$0.07	\$4,263.28
	Generator sets, w/battery, charger, muffler and transfer switch, gas/gasoline operated, 3 phase, 4 wire, 277/480 V, 15 kW	6.51		\$0.07	\$4,263.28
E Equipment & Furnishin			0.3%	\$0.28	\$17,580.14
E1020	Institutional Equipment			\$0.28	\$17,580.14
	Architectural equipment, laboratory equipment, counter tops, stainless steel	68.58		\$0.28	\$17,580.14
E1090	Other Equipment			\$0.00	\$0.00
F Special Construction			0.0%	\$0.00	\$0.00
G Building Sitework			0.0%	\$0.00	\$0.00
Sub Total			100%	\$98.27	\$6,065,405.52
Contractor's Overhead & Profit			25.0 %	\$24.57	\$1,516,351.38
Architectural Fees			7.0 %	\$8.60	\$530,722.98
User Fees			0.0 %	\$0.00	\$0.00
Total Building Cost				\$131.44	\$8,112,479.88

Appendix V: SITE PHOTOGRAPHS



1 - Venable Elementary School



2 - Venable annex



3 - Asphalt pavement west side looking south



4 - Asphalt pavement - note cracking



5 - Asphalt pavement - note cracking



6 - Asphalt pavement - note cracking



7 - Typical concrete sidewalk



8 - Typical concrete sidewalk - note cracking



9 - Typical concrete sidewalk



10 - Curb ramp



11 - Typical concrete sidewalk - note cracking



12 - Typical concrete sidewalk - note deterioration



13 - Brick paver sidewalk



14 - Brick paver sidewalk



15 - Concrete stairs at the west side of the building



16 - Typical landscaping



17 - Typical landscape



18 - Dumpster area



19 - Playground at south end of site



20 - Playground at northeast end of site



21 - Playground at southeast end of site



22 - Building exterior west side of the building



23 - Building exterior south side of the building



24 - Building exterior - note rotten through cornice work



25 - Building exterior - note rotten through cornice work



26 - Building exterior - note deterioration




27 - Building exterior - note deterioration



28 - Building exterior - note efflorescence



29 - Building exterior - note rotten through cornice work



30 - Building exterior - note step cracking in brick



31 - Building exterior - note cracking



32 - Building exterior - note efflorescence



33 - Building exterior - note rotten through cornice work



34 - Building exterior - note peeling paint



35 - Venable annex building exterior



36 - Main entrance doors at west side of the building




37 - Entrance doors at north side of the building



38 - Typical personnel door



39 - Typical exterior window



40 - Typical exterior windows



41 - Typical exterior window - note peeling paint



42 - Typical exterior window - note peeling paint



43 - Typical exterior window - note peeling paint



44 - Typical exterior window security fence - note peeling paint



45 - Typical exterior window security fence - note peeling paint



46 - Slate shingle roofing system



47 - Slate shingle roofing system



48 - Slate shingle roofing system - note damaged and misaligned shingles



49 - Metal roofing system - south addition



50 - water leakage



51 - Gas domestic water heaters



52 - Boilers located in main utility room



53 - Cooling tower located on east side of the building



54 - Condenser unit at annex



55 - Air Handler Unit located in main utility room



56 - Typical older Water Source Heat Pump



57 - Typical newer Water Source Heat Pump



58 - Typical newer Water Source Heat Pump



59 - Split system located in main utility room




60 - Space heater located in main utility room



61 - Electric utility transformer



62 - Electric utility meter



63 - Main electrical switchgear



64 - Emergency power generator



65 - Emergency power transfer switch



66 - Typical electric circuit breaker panel



67 - Elevator located at center of building



68 - Elevator machine and controls



69 - Fire sprinkler system



70 - Fire sprinkler pump controller



71 - Fire sprinkler pump controller



72 - Fire sprinkler supply



73 - Typical fire sprinkler head



74 - Typical fire extinguisher



75 - Typical fire extinguisher



76 - Fire Department Connection



77 - Fire Pump Test Connection



78 - Fire alarm control panel



79 - Typical fire alarm bell and strobe



80 - Typical fire alarm pull station



81 - Typical smoke detector



82 - Typical gas meter



83 - Interior finishes main office area



84 - Interior finishes corridor area



85 - Interior finishes classroom area



86 - Interior finishes classroom area



87 - Accessible lift



88 - Accessible restroom



89 - Accessible parking space



90 - Accessible ramp at south end the site

Appendix VI: RESUMES

Michael G. Doyle, AIA

Principal Architect – Facilities Department

EDUCATION

Bachelor of Architecture, 1987, Architecture, Virginia Polytechnic Institute and State University, Blacksburg, VA

REGISTRATIONS

Registered Architect: AZ, DC, MD, VA, NC, IL
The Leadership in Energy and Environmental Design (LEED) Accredited Professional: 2009

Mr. Doyle serves as a Principal Architect for the Facilities Engineering Group in ECS Chantilly. He has over 25 years of experience in the construction industry, and his expertise includes the Americans with Disabilities Act, Property Condition Surveys, Pre and Post Construction Survey Services, Pavement Assessments, and Third-Party Plan Review. He has worked with numerous government agencies and has significant experience with local government and educational facilities; commercial high-rise buildings; multi-unit, residential, and correctional facilities. Mr. Doyle also has had experience on several high-profile historic projects, including the Jefferson Memorial, the Tivoli Theater, the Tariff Building, The White House, the Court of Appeals in Washington, DC; the Valley Bank Building in Leesburg, Virginia; and the Shenandoah Courthouse at Woodstock, Virginia.

Property Condition Assessments - Mr. Doyle has extensive experience performing property condition assessments from small commercial properties, large high rise buildings, to government-owned properties. Mr. Doyle has performed assessment in general accordance with ASTM E 2018, Standard Guide for Property Condition Assessments: Baseline Property Condition Assessment Process. Mr. Doyle also has experience in performing property condition assessments in accordance with lender and specific client requirements. Mr. Doyle has worked with teams of experts in providing detailed reports and simple reserve analysis for properties.

RELEVANT PROJECT EXPERIENCE

Darien Lake, Darien Center, NY – Mr. Doyle was the Principal Architect for the property assessment of the Darien Lake amusement park. The property included over 200 buildings including buildings within the park, maintenance and administration buildings, hotel, campground buildings, and sewer treatment center.

Ballston Park Apartments, Arlington, VA (2014) - originally developed in 1938, this complex includes 50 two-story apartment buildings, one three-story apartment building, one single-family residence, and a single-story office/clubhouse. A PCA and a Phase I Environmental Site Assessment was conducted and documented.

Hyatt House Lodging, Sterling, VA (2014) - This six-story, 162-room, 98,793-square-foot hotel with surface parking was constructed in 2007 as a Sierra Suites and subsequently converted to a Hyatt House. Recreational facilities include a swimming pool, fitness center, a grill area, and a fire pit. Building systems observed per ASTM E 2018 included site conditions, the structural frame and building envelope; plumbing, mechanical and electrical systems, vertical transportation Systems, life safety and fire protection, and ADA Considerations. A Phase I Environmental Site Assessment was also conducted.

WHMO Facilities Assessment, Washington, DC (2015) - This is a privately owned, government-leased facility with a sensitive mission. The structure is believed to be a 1920s vintage building designed as a multi-story car dealership. The government has occupied this space continuously since 1963. Mr. Doyle conducted a survey of the complete facility, identified and documented areas of concerns. He also provide a recommendation for remediation for each area of concern, a Rough Order Magnitude (ROM) cost for remediation, and categorized each area of concern as critical, non-critical or aesthetic.

ADDITIONAL PROJECT EXPERIENCE

- City of Charlottesville Portfolio, Charlottesville, VA
- Liberty Park, Herndon, VA
- Oakcrest School, McLean, VA
- Signature Flight Support, Arlington, VA
- The Gap, Washington, DC
- Lanham Crossing, Lanham, MD
- ZIM American Headquarters Building, Suffolk, VA
- The Portrait Building, Washington, DC
- The Aventine of Alexandria, Alexandria, VA



DONALD GOGLIO

CODE COMPLIANCE PROJECT MANAGER



CERTIFICATIONS

Master Plumber
Master Gasfitter
Cross Connection Technician
Commercial Building Inspector
Commercial Plumbing Inspector
Commercial Mechanical Inspector
Accessibility Inspector/Plan
Reviewer

Fire Inspector I and II
LEED Green Associate
CPR/First Aid Training
OSHA 30 hr Training

SKILLS

Code Compliance
Construction Administration
Special Inspection Services
Condition Assessments
Forensic Consultation

PROFESSIONAL MEMBERSHIPS

American Wood Council
USGBC

EDUCATION

Montgomery College, 1991
Silver Spring, MD

YEARS OF EXPERIENCE

ECS: <1 Other: 38

PROFESSIONAL PROFILE

Mr. Goglio has 38 years of construction, mechanical trade, and management experience. He manages code compliance projects, including reviewing plans, providing technical support, and conducting inspections.

PROJECT EXPERIENCE

Fort Lee AIT Barracks, Ft. Lee, VA – Quality Control Manager – The Fort Lee AIT Barracks project is a soldiers' basic combat training facility for over 1,200 Army personnel. The complex is a cohesive development, providing both housing and affiliated functions for soldiers in the AIT program. In addition to housing, the facility includes an outdoor jogging track, physical training pits, and access drivers and parking areas that meet USACE requirements. The project's five-story brick buildings meet DoD Minimum Antiterrorism Standards for Buildings and obtained LEED® Gold certification from the US Green Building Council. The Fort Lee project is part of the Northeast Region Multiple Award Task Order Contract (MATOC).

Terrapin Row, College Park, MD – Assistant Superintendent – Terrapin Row is a transformative student housing complex located on the University of Maryland's historic South Campus. The mixed-use community features 1,493 beds across 418 apartments as well as a 489-space parking garage. Terrapin Row boasts ample amenities centered around a college lifestyle, including a swimming pool, volleyball court, outdoor kitchens and fire pits, exterior TVs, a fitness center, bike storage, a cyber cafe and game room, and numerous live-learn spaces. The multi-phase project consists of seven buildings and encompasses a pedestrian and bike-friendly Village Green surrounded by over 11,856 square feet of retail space. The Village Green flows into a grand stairway and amphitheater that opens to a pedestrian plaza to welcome pedestrians towards the main academic centers of campus.

The Hartley at the Parks, Washington, DC – Assistant Superintendent – The Hartley is a 323-unit mixed-use apartment community with a Whole Foods Market as its retail anchor in Northwest DC. This six-story community consists of five stories of wood framing over a one-story concrete podium with 317 apartments and six townhomes. It is a part of The Parks at Walter Reed, a mixed-use master-planned redevelopment of the 66-acre historic Walter Reed Army Medical Center with 2,200 residential units plus office and retail. The Hartley features two interior courtyards: the north courtyard includes pool and amenity space, and the south courtyard includes a Zen Garden. The second-floor amenity space includes a lounge, multi-purpose room, fitness center, and pet spa. The studio, one-, two-, and three-bedroom units feature high-end finishes, including quartz countertops and EnergyStar® appliances.



DONALD GOGLIO

CODE COMPLIANCE PROJECT MANAGER



CERTIFICATIONS

Master Plumber
Master Gasfitter
Cross Connection Technician
Commercial Building Inspector
Commercial Plumbing Inspector
Commercial Mechanical Inspector
Accessibility Inspector/Plan
Reviewer
Fire Inspector I and II
LEED Green Associate
CPR/First Aid Training
OSHA 30 hr Training

SKILLS

Code Compliance
Construction Administration
Special Inspection Services
Condition Assessments
Forensic Consultation

PROFESSIONAL MEMBERSHIPS

American Wood Council
USGBC

EDUCATION

Montgomery College, 1991
Silver Spring, MD

YEARS OF EXPERIENCE

ECS: <1 Other: 38

PROFESSIONAL PROFILE

Mr. Goglio has 38 years of construction, mechanical trade, and management experience. He manages code compliance projects, including reviewing plans, providing technical support, and conducting inspections.

PROJECT EXPERIENCE

- Fort Lee AIT Barracks, Ft. Lee, VA
- Terrapin Row, College Park, MD
- The Hartley at the Parks, Washington, DC
- River Point, Washington, DC
- Juniper, Columbia, MD
- The Smith, King of Prussia, PA
- Banner Hill, Baltimore, MD
- Jefferson Square, Baltimore, MD
- Metropolitan at Largo Station, Largo, MD
- The Village at Leesburg, Leesburg, VA
- The Elms at Clarksburg Village, Clarksburg, MD
- Hidden Creek, Gaithersburg, MD
- Paramount, Gaithersburg, MD
- Thayer & Spring, Silver Spring, MD





William R. Pratt, PE

*Principal Engineer, ECS Mid-Atlantic, LLC
Professional-In-Charge*

EDUCATION

Bachelor of Science, 1989, Mechanical Engineering, University of Massachusetts

REGISTRATIONS

Professional Engineer: DC, VA, MD

ICC Commercial Building, Plumbing, and Mechanical Inspector

Mr. Pratt serves as Senior Project Engineer for ECS Mid-Atlantic, LLC. Mr. Pratt is responsible as the Professional-In-Charge of the code compliance group and provides supervision of code compliance inspection programs for the local jurisdictions. Additionally, he oversees execution of project management for construction materials testing, property condition assessments.

PROPERTY CONDITION ASSESSMENTS - Bill has extensive experience in performing property condition assessments for a variety of properties and structures. These assessments include evaluation of site improvements, building components, roofing, pavements, electrical systems, mechanical systems, and HVAC systems. He performs assessment in general accordance with ASTM E 2018 – 08, Standard Guide for Property Condition Assessments: Baseline Property Condition Assessment Process. Bill also has experience in performing property condition assessments that meet with lender and specific client requirements. He works with teams of experts in providing detailed reports and simple reserve analysis for properties.

SELECT PROJECT EXPERIENCE – PCA

- City of Charlottesville, VA - 51 Property Portfolio including schools, libraries, museums, fire and police stations, and court buildings
- Home Properties 800+ Apartment Units, 4-Property Portfolio to Freddie Mac Standard, Hampton and Virginia Beach, VA
- Boulders Office Park 300,000+ SF, 3-Property Portfolio, Richmond, VA
- Darien Lake Theme Park, Darien Center, NY
- Madison Place Office Building, Alexandria, VA
- King of Glory Lutheran Church, Williamsburg, VA
- Comfort Inn, Charlottesville, VA
- The Wisconsin Building, Washington, DC

SELECT PROJECT EXPERIENCE – CODE COMPLIANCE AND SPECIAL INSPECTIONS

- City Center DC, Washington, DC
- DC Courts Judiciary Square, IDIQ Contract, Washington, DC
- Hilton Garden Inn, Washington, DC
- Waterfront Mall, Washington, DC
- 4th Street Reconstruction, Washington, DC
- Sibley Memorial Hospital Addition, Cancer Center, Washington, DC
- Washington Headquarters Services, Arlington, VA
- Walmart #5968-00, Washington, DC
- Progression Place, 7th Street, NW, Washington, DC
- National Gallery of Art, Washington, DC
- City Market @ O, Washington, DC

